

MARY ESTHER, FLORIDA

ILS or LOC RWY 36

LOC I-HRT 111.3	APCH CRS 358°	Rwy ldg TDZE Arprt Elev 9600 37 38	AL-734 [USAF]	HURLBUR FLD (KHRT)
DME or RADAR required for S-LOC 36.			ALSF-1 	MISSED APPROACH: Climb to 1800 on HRT TACAN R-360 to ORTIZ/11 DME and hold.
* When ALS inop, increase RVR to 40, vis to ¼ mile.				
ATIS 134.475 360.675	EGLIN APP CON 125.1 281.45 (271°-089°) 132.1 360.6 (090°-270°)		HURLBUR TOWER 126.5 351.675	GND CON 123.975 275.8
** When ALS inop, increase CAT ABC RVR to 50, vis to 1 mile; CAT DE RVR to 60, vis to 1 ¼ miles.				
EMERG SAFE ALT 100 NM 3700				
1800 ↑ HRT R-360	ORTIZ HRT 11			
TACAN	GFROG 1.3	WETGO 5.2	TESNE 7	SAMMY 15
6 NM		3.9 NM		

ELEV 38	TDZE 37
HURL Rwy 18-36	
FAF to MAP 3.9 NM	
Knots	60 90 120 150 180
Min:Sec	3:54 2:36 1:57 1:34 1:18

SE-3, 01 DEC 2022 to 29 DEC 2022

SE-3, 01 DEC 2022 to 29 DEC 2022

MARY ESTHER, FLORIDA

30°26'N-86°41'W

HURLBUR FLD (KHRT)

Amdt 2 05APR07

ILS or LOC RWY 36