

V

DEPARTURE ROUTE DESCRIPTION

<u>TAKEOFF RWY 6:</u> Climbing left turn direct to cross BOLME at or above 5000 and at or below 6000, then track as depicted to NAGGS. Maintain 6000.

TAKEOFF RWY 18: Climbing left turn direct COWDA, then track as depicted to NAGGS. Maintain 6000.

TAKEOFF RWY 24: Climbing left turn direct COWDA, then track as depicted to NAGGS. Maintain 6000.

TAKEOFF RWY 36: Climbing left turn direct ERUBE, then track as depicted to NAGGS. Maintain 6000.

<u>Alternative</u>: Initial RADAR vector climb-out option to rejoin RNAV routing at BOLME at or above 5000. All runways: Fly runway heading, maintain 6000. Request radar vector departure option with CLNC DEL upon initial contact.