60

## CONTINUED FROM PRECEDING PAGE

COMMUNICATIONS: ATIS 127.75 (207-561-2524) UNICOM 122.95

RC0 122.2 (BANGOR RADIO) R APP/DEP CON 118.925 124.5

TOWER 120.7 GND CON 121.9 CLNC DEL 135.9

AIRSPACE: CLASS C svc. ctc. APP CON

RADIO AIDS TO NAVIGATION: NOTAM FILE BGR

(VH) (H) VORTACW 114.8 BGR Chan 95 N44°50.51′ W68°52.44′ 155° 2.8 NM to fld. 360/19W.

ILS/DME 109.5 I-JVH Chan 32 Rwy 15. Class IIIE. DME also serves Rwy 33.

ILS/DME 109.5 I-BGR Chan 32 Rwy 33. Class IIE. DME also serves Rwy 15. DME unusable byd 26° r of course.

HELIPAD H1: H100X100 (CONC)

LUCKY LANDING MARINA SPB (Ø6B) 7 N UTC-5(-4DT) N44°54.42′ W68°48.30′

115 NOTAM FILE BGR

WATERWAY 02W-20W: 15000X4000 (WATER)

WATERWAY 02W: Rgt tfc. SERVICE: FUEL 100LL

SEAPLANE REMARKS: Attended Apr-Oct dalgt hrs, unattended Nov-Mar. To verify conditions and for fuel after hrs call

207-951-2406. Water Idg area not marked. Rwy 02W wires on shore marked.

AIRPORT MANAGER: (207) 951-2406 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2521.

BANKS (See SWANS ISLAND on page 88)

## **BAR HARBOR**

HANCOCK CO/BAR HARBOR (BHB)(KBHB) 8 NW UTC-5(-4DT) N44°26.98′ W68°21.69′

83 B Class IV, ARFF Index A NOTAM FILE BHB RWY 04-22: H5200X100 (ASPH) D-72, 2S-91, 2D-100

PCN 40 F/D/X/T HIRI

RWY 04: REIL, VASI(V4L)-GA 3.0° TCH 55', Trees.

RWY 22: MALSF. VASI(V4L)-GA 3.0° TCH 55'.

RWY 17-35: H3363X75 (ASPH) S-13, D-20 1.1% up N

RWY 17: Thid dsplcd 684'. Tree. RWY 35: Thid dsplcd 111'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 04: TORA-5200 TODA-5200 ASDA-5200 LDA-5200 RWY 22: TORA-5200 TODA-5200 ASDA-5200 LDA-5200

SERVICE: S4 FUEL 100LL, JET A 0X3, 4 LGT ACTVT MALSF Rwy 22, REIL Rwy 04, VASI Rwy 04 and 22, HIRL Rwy 04-22-122.7.

NOISE: Durg VFR conds when wind speed less than 5 kts as rprtd by AWOS or UNICOM, all acft using Rwy 04-22 are reqd to tkof and land on Rwy 22 for noise abatement procs.

AIRPORT REMARKS: Attended 1300-2300Z‡. Birds on and invof arpt. Grass areas unavbl for acft ops. Seaplane ramp unavbl for acft ops exc PPR 207-667-7329. Ficon not mnt Mon-Fri 0200-1230Z‡,

wkends & hols. Rwv 04-22 due to hump at midpoint, opposite ends of rwy not visible at gnd level. Rwy 17-35 not avbl for skedd acr ops

(Idg and tkof) more than 9 pax seats or unsked acr ops at least 31 pax seats. Rwy 17-35 N of Twy H avbl for acr ops more than 9 pax seats for taxi only. 48 hr PPR for unsked acr ops at least 31 pax seats. Ctc amgr. PPR for overweight ldgs. PPR for unsked acr ops rqrg 14 CFR 139 ARFF. Ctc amgr. Twy B clsd to all acft greater than 10,000 lbs. Twys F and Twy G clsd Dec 1-Mar 31 annually.

AIRPORT MANAGER: 207-667-7329

WEATHER DATA SOURCES: AWOS-3PT 118.35 (207) 667-7364.

COMMUNICATIONS: CTAF/UNICOM 123.0

RBANGOR APP/DEP CON 133.6

**CLNC DEL** 119.9

CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2521.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE BGR.

BANGOR (VH) (H) VORTACW 114.8 BGR Chan 95 N44°50.51′ W68°52.44′ 156° 32.2 NM to fld. 360/19W.

ILS/DME 108.3 I-BHB Chan 20 Rwy 22. Class IB. Unmonitored.

3 €3 **(3** €3 €3 M €3 43 €3 €3 €3 **3** 43 €3 €3 63 43 €3 43 63 €3 a €3 3 / 3 €3 **(3** €3 €3 43 €3 43 **43** 

HALIFAX

**HALIFAX** 

IAP

H-11D, L-32I