

TACAN Y RWY 23

TACAN NRB
Chan 51

APCH CRS
221°

Rwy Idg
8001
TDZE
15
Arpt Elev
15

AL-722 [USN]

MAYPORT NS (ADM DAVID L. MC DONALD FLD) (KNRB)

Visibility reduction by helicopters NA.

MISSED APPROACH: Climbing left turn to 2000
via NRB TACAN R-081 to BERGE and hold.

ATIS ★
236.775

JACKSONVILLE APP CON
124.9 308.4

TOWER ★
118.75 239.30

GND CON
126.5 233.7

ASR/PAR

CRG feeder route requires turn in hold.

CAUTION: Procedure not authorized at night when the VGSI is inop, unless the station has an approved observer watching for marine traffic in the St. John's River channel.

CRG 114.5 Chan 92

CRAIG MUNI 1074 A

MAYPORT Chan 51 NRB

HELES NRB 10

BERGE NRB 11 2000

CAUTION: Vessels with masts up to 150' transiting the St. Johns River inside of NRB 2 DME.

EMERG SAFE ALT 100 NM 2800

2000 NRB R-081

BERGE NRB 11

TACAN

LEBAF 1

JERBI 4

IKECA 8

MUKOE 10

1100

1700

221°

3.01°

TCH 48

3 NM

CATEGORY	A	B	C	D
S-23	520-1 505 (600-1)	520-1½ 505 (600-1½)		
CIRCLING	560-1 545 (600-1)	560-1½ 545 (600-1½)	620-2 605 (700-2)	

ELEV 15

TDZE 15

REIL Rwy 5-23

HIRL Rwy 5-23

MAYPORT, FLORIDA

30°23'N-81°25'W MAYPORT NS (ADM DAVID L. MC DONALD FLD) (KNRB)

Amtd 5 07OCT21

TACAN Y RWY 23