

BELLINGHAM**BELLINGHAM INTL** (BLI)(KBLI) 3 NW UTC-8(-7DT) N48°47.56' W122°32.25'

171 B TPA—See Remarks AOE Class I, ARFF Index B NOTAM FILE BLI

RWY 16-34: H6700X150 (ASPH-GRVD) S-75, D-160, 2S-175,
2D-250 PCN 57 F/A/W/T HIRL**RWY 16:** MALSR. PAPI(P4L)—GA 3.0° TCH 50'. RVR-T Rgt tfc.**RWY 34:** REIL. PAPI(P4L)—GA 3.0° TCH 50'. RVR-R**RUNWAY DECLARED DISTANCE INFORMATION****RWY 16:** TORA-6700 TODA-6700 ASDA-6700 LDA-6700**RWY 34:** TORA-6700 TODA-6700 ASDA-6700 LDA-6700**SERVICE:** S7 FUEL 100LL, JET A LGT When twr clsd ACTIVATE HIRL

Rwy 16-34, MALSR Rwy 16 and REIL Rwy 34—CTAF.

NOISE: NS ABTMT procedures in effect ctc ops at 360-739-1944 or at
www.flybli.com/noise.**AIRPORT REMARKS:** Attended continuously. Birds and coyotes on and in/ov
arpt movement areas. PPR for unscheduled air carrier ops with more
than 30 pax seats ctc ops at 360-739-1944. Twy A btn Twy E and
Twy F clsd to acct winspan more than 118'. Portions of Twy A at Twy
G and Twy J not vsbl from twr. Air carrier ops use Twy A, Twy B, Twy
C, Twy D West of Twy E, Twy E, Twy F West of Twy A, Twy G, and Twy
H. Coml ramp clsd to pvt acct. TPA—1200 (1030) fixed wing,
700(530) helicopter, 2000(1830) turbo. Ldg fee over 7,500 lbs.
Flight Notification Service (ADCUS) avbl.**AIRPORT MANAGER:** (360) 676-2500**WEATHER DATA SOURCES:** ASOS (360) 671-8688**COMMUNICATIONS:** CTAF 124.9 ATIS 134.45 360-647-5939 UNICOM 122.95

RCO 122.2 (SEATTLE RADIO)

Ⓡ VICTORIA TERMINAL APP/DEP CON 132.7


TOWER 124.9 (1500-0630Z±) GND CON 127.4

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Victoria trml on 133.95 or at 604-586-4561.**AIRSPACE:** CLASS D svc 1500-0630Z±; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE BLI.**WHATCOM (H) (H) VORTACW** 113.0 HUH Chan 77 N48°56.72' W122°34.76' 150° 9.3 NM to fld. 82/20E.

TACAN AZIMUTH unusable:

155°-165° byd 15 NM blo 6,000'

ILS/DME 108.5 I-BLI Chan 22 Rwy 16. Class IA. ILS DME unusable beyond 30° left of course.

SEATTLE
H-1B, L-1E
IAP, AD**FLOATHAVEN SPB** (@W7) 6 SE UTC-8(-7DT) N48°44.14' W122°20.40'

307 NOTAM FILE SEA

WATERWAY 12W-30W: 10000X4000 (WATER)**SERVICE:** S4**NOISE:** Avoid flying over noise sensitive area during tkf and ldg.**SEAPLANE REMARKS:** Attended dalgt hrs. Canoe, sailboat, drone and hang glider activity in/ov arpt. For airframe repairs call
206-909-7299 prior to arrival to arrange svcs. Land and tkf in the center of the lake.**AIRPORT MANAGER:** 206-909-7299**COMMUNICATIONS:** CTAF 122.9

VICTORIA TERMINAL APP/DEP CON 132.7 290.8 604-586-4560

SEATTLE

BOEING FLD/KING CO INTL (See SEATTLE on page 247)**BOWERMAN** (See HOQUIAM on page 222)**BOWERS FLD** (See ELLENSBURG on page 215)