

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS B See VFR Terminal Area Chart.

RADIO AIDS TO NAVIGATION: NOTAM FILE CVG.

(L) (L) VORTACW 117.3 CVG Chan 120 N39°00.96' W84°42.20' 044° 2.6 NM to fld. 878/4W.

ILS/DME 111.9 I-JRN Chan 56 Rwy 09. Class ID.

ILS/DME 111.55 I-SIC Chan 52(Y) Rwy 18C. Class IIE.

ILS/DME 110.15 I-CJZ Chan 38(Y) Rwy 18L. Class IA. LOC unusable byd 25° left of course.

ILS/DME 110.75 I-CJN Chan 44(Y) Rwy 18R. Class IIE.

ILS 108.7 I-JDP Rwy 27. Class IIE. LOC unusable byd 20° right of course.

ILS/DME 109.9 I-CVG Chan 36 Rwy 36C. Class IIIE.

ILS/DME 110.75 I-VAC Chan 44(Y) Rwy 36L. Class IIE.

ILS/DME 110.35 I-EEI Chan 40(Y) Rwy 36R. Class IIIE.

CUBLA N39°21.21' W83°52.55' NOTAM FILE ILN.

CINCINNATI

NDB (LOMW) 299 HW 048° 5.9 NM to Wilmington Air Park. 996/7W.

L-27E

CUYAHOGA CO (See CLEVELAND on page 268)**DAHIO TROTWOOD** (See DAYTON on page 275)**DARKE CO** (See VERSAILLES on page 316)

DAYTON

DAHIO TROTWOOD (I44) 7 W UTC-5(-4DT) N39°45.91' W84°20.58'

CINCINNATI

925 NOTAM FILE DAY

RWY 04-22: H2900X52 (ASPH)

RWY 04: Crops.

RWY 22: Trees.

AIRPORT REMARKS: Unattended. Ultralights and pwrld prchts on and invof arpt. Rwy 04-22 numerous cracks in pavement with 3' vegetation. 8' crops along entire length Rwy 04-22, 10' from rwy edge, both sides. Mowed path from Rwy 04 end to hngr area not suitable for acft. Twy from midfield to hgr area, 35' clnc between 8' crops. Wind indicator: LDI tetrahedron (tet) OTS/unrel.

AIRPORT MANAGER: 937-604-2619**COMMUNICATIONS: CTAF/UNICOM** 122.8Ⓡ **COLUMBUS APP/DEP CON** 118.85**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.**COMM/NAV/WEATHER REMARKS:** Columbus APCH CTL TEL# 614-338-8537**DAYTON TRANSPORTATION CENTER HELIPORT** (5D7) 0 N UTC-5(-4DT) N39°45.45' W84°11.30' CINCINNATI

800 B NOTAM FILE DAY

HELIPAD HL: H40X40 (CONC) S-4.5 PERIMETER LGTS**SERVICE:** LGT Actvt perimeter lgts and rotating bcn-CTAF.

HELIPORT REMARKS: Unattended. Rooftop: 40' x 40' concrete pad within 80' x 60' landing/takeoff area. Maximum landing weight 4500 lbs. Ingress/egrees 005-175. Rwy H1 mkg faded and incomp.

AIRPORT MANAGER: 937-454-8299**COMMUNICATIONS: CTAF** 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.**DAYTON/PHILLIPSBURG** (3I7) 13 NW UTC-5(-4DT) N39°54.80' W84°24.02'

CINCINNATI

1028 B NOTAM FILE DAY

L-27E

RWY 03-21: H3000X40 (ASPH) LIRL

IAP

RWY 03: REIL. Thld dspld 130'. Tree.

RWY 21: REIL.

SERVICE: S4 FUEL 100LL, JET A OX 1, 2

AIRPORT REMARKS: Attended Mon-Sat 1400-2200Z, Sun 1500-2200Z. Unatndd New Years, Easter, Thanksgiving, Christmas. 100LL avbl H24 self svc via credit card. Jet A avbl on req. Rwy 03-21 mks nstd basic due to nrs sml size and not lctd at thr; cntrln spacing. Rwy 03 dtthr mkd with white line with no arrows.

AIRPORT MANAGER: 937-884-9795**COMMUNICATIONS: CTAF/UNICOM** 122.7Ⓡ **COLUMBUS APP/DEP CON** 118.425**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.

(L) (L) VOR/DME 114.5 DQN Chan 92 N40°00.99' W84°23.81' 183° 6.2 NM to fld. 989/1W.

DME unusable:

Byd 35 NM blo 2,900'