
SALEM AIRPARK INC (38D) 3 N UTC-5(-4DT) N40°56.88' W80°51.72'

1162 NOTAM FILE CLE

RWY 10L-28R: H3404X50 (ASPH) S-8 LIRL(NSTD) 0.3% up E

RWY 10L: Trees.

RWY 28R: Thld dsplcd 266'. Hill.

RWY 10R-28L: 2550X60 (TURF) 0.4% up E

RWY 10R: Trees.

RWY 28L: Road.

SERVICE: FUEL 100LL LGT Actvt nstd LIRL Rwy 10L-28R—CTAF. Rwy 10L-28R nstd LIRL due to layout and colors; Rwy 10L lgttd 238' from rwy end; Rwy 28R lgttd 330' from rwy end with 360° green lghts.

AIRPORT REMARKS: Unattended. Deer, birds, and wildlife on and infov arpt. Dragstrip 3500' southeast looks like arpt. All pavement restricted acft max gwt less than 8000 lbs. Rwy 10R-28L (turf): ctc amgr for rscd prior to use; twy connector at east end unusbl due to pavement heave; unmkd ditch on north side. Rwy 10R-28L rwy ends not marked. Rwy 10L-28R marking non-standard due to yellow DTHR. Rwy 10L-28R only 2829 ft avbl for ngt ops. Rwy 28R: acft on turn frm downwind to base may be obscd by trees in apch.

AIRPORT MANAGER: 330-402-1136**COMMUNICATIONS:** CTAF/UNICOM 122.7

Ⓡ CLEVELAND APP/DEP CON 125.5 (1100-0500Z‡) ctc 216-352-2323.

Ⓡ CLEVELAND CENTER APP/DEP CON 120.775 (0500-1100Z‡) ctc Cleveland ARTCC at 440-774-0223.

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE YNG.

YOUNGSTOWN (L) (L) VORTACW 109.0 YNG Chan 27 N41°19.86' W80°40.48' 205° 24.5 NM to fld. 1159/5W.

VOR unusable:

015°-179° blo 5,000'

180°-014° byd 25 NM blo 5,000'

SANDUSKY CO RGNL (See FREMONT on page 283)

SEAGATE HELISTOP HELIPOINT (See TOLEDO on page 313)

SEBRING
TRI-CITY (3G6) 1 SE UTC-5(-4DT) N40°54.36' W81°00.00'

1188 NOTAM FILE CLE

RWY 18-36: H2768X45 (ASPH) LIRL(NSTD)

RWY 36: Pole.

SERVICE: FUEL 100LL LGT Actvt NSTD LIRL Rwy 18-36—CTAF. Rwy 18-36 NSTD LIRL due to layout, colors and non-frangible fixtures.

AIRPORT REMARKS: Unattended. Deer, birds, & wildlife on & infov arpt. Fuel avbl upon request, call amgr. Rwy 18-36 excessive cracking, vegetation thru cracks & joints, & uneven rough pavement. Rwy 18 nstd basic due to nrs layout & size. Cntrln faded. Rwy 36 nstd basic due to nrs layout & size. Cntrln faded.

AIRPORT MANAGER: 330-428-1269**COMMUNICATIONS:** CTAF 122.9

Ⓡ CLEVELAND APP/DEP CON 125.5 (1100-0500Z‡)

Ⓡ CLEVELAND CENTER APP/DEP CON 120.775 (0500-1100Z‡) ctc Cleveland ARTCC at 440-774-0223.

CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.

RADIO AIDS TO NAVIGATION: NOTAM FILE CAK.

AKRON (L) (L) VORW/DME 114.4 ACO Chan 91 N41°06.47' W81°12.09' 147° 15.2 NM to fld. 1197/4W.

DME unusable:

Byd 10 NM

SENECA CO (See TIFFIN on page 312)

DETROIT

L-30G

IAP

DETROIT

L-29B

IAP