

TROY**RENSELAER CO** (5B7) 6 SE UTC-5(-4DT) N42°41.50' W73°34.80'

NEW YORK

440 NOTAM FILE BTV

RWY 18-36: H2670X50 (ASPH) S-8**RWY 18:** Trees.**RWY 36:** Trees.

AIRPORT REMARKS: Unattended. Tran acft call 518-596-5947 for fld conditions prior to arrival. Deer and birds on and in/ovf arpt. Surrounding terrain slopes down to rwy, due to higher surrounding terrain recommend use of the following procedures, departing Rwy 36, use best angle of climb speed until well clear of residential area north of Rwy 36, arrivals Rwy 18 maintain sufficient alt on final so as to avoid low alt and/or high power over residential area which underlies final apch to Rwy 18. Departures Rwy 18 and arrivals Rwy 36 use normal procedures. Rwy 18-36 widespread svr cracking and distortion. Svr spalling and faulting. Widespread vegetation. Rwy 18 first 40' overgrown with grass. Rwy 18 markings not visible. Rwy 36 marking numbers faded.

AIRPORT MANAGER: (518) 596-5947**COMMUNICATIONS:** CTAF/UNICOM 122.7**CLEARANCE DELIVERY PHONE:** For CD ctc Albany Apch at 518-862-2299.**UTICA/FRANKFORT****FRANKFORT-HIGHLAND** (6B4) 4 SE UTC-5(-4DT) N43°00.97' W75°10.17'

NEW YORK

1325 NOTAM FILE BUF

RWY 13-31: H2750X60 (ASPH) S-12 LIRL 0.4% up NW**RWY 13:** Thld dsplcd 200'. Trees.**RWY 31:** Thld dsplcd 205'.**SERVICE:** FUEL 100LL

AIRPORT REMARKS: Unattended. Self-serve fuel. Geese on and in/ovf arpt during spring and fall. Model plane club opr on arpt. Rwy 31 has 120' dropoff 90' from thld on both sides. LIRL Rwy 13-31 not avbl to tran acft.

AIRPORT MANAGER: 315-796-6257**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc Syracuse Apch at 315-455-6218.**UTICA** N43°01.59' W75°09.87' NOTAM FILE BUF.

NEW YORK

(L) **TACAN** 111.2 UCA Chan 49 319° 16.4 NM to Griffiss Intl. 1420/0W.

L-32G

RCO 122.2 (BUFFALO RADIO)**WALKKILL****KOBELT** (N45) 2 NE UTC-5(-4DT) N41°37.45' W74°08.50'

NEW YORK

420 B NOTAM FILE ISP

RWY 03-21: H2864X50 (ASPH) S-13**RWY 03:** Trees.**RWY 21:** Trees.**SERVICE:** FUEL 100LL

AIRPORT REMARKS: Unattended. Arpt clsd to acft 13,500 lbs and over. Deer on and in/ovf arpt. PJE at arpt 3.0 NM radius SFC-14,500'. Rwy 03 has access road 16' from thld both sides. Rwy center width of 30' in good condition, 10' width on both sides of centerline in poor condition with extensive cracks and vegetation. Rwy 03-21 slight depression in grass areas opposite south end of rwy. Rwy center 30' in fair condition, outside edges beyond this in poor condition. 18' wide parallel twy, stub connectors to rwy between ends in poor condition.

AIRPORT MANAGER: 845-255-1087**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc New York Apch at 516-683-2448.**WARSAW****R & R AERO** (5R5) 3 WSW UTC-5(-4DT) N42°43.25' W78°11.08'

DETROIT

1650 NOTAM FILE ISP

RWY 10-28: 4000X140 (TURF)**RWY 28:** Trees. Rgt tfc.**AIRPORT REMARKS:** Attended irregularly. Clsd during snow months (Nov-Apr).**AIRPORT MANAGER:** 530-864-3737**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0490.