

AUBURN MUNI (AUN)(KAUN) 3 N UTC-8(-7DT) N38°57.29' W121°04.90'
1538 B TPA—See Remarks NOTAM FILE AUN
RWY 07-25: H3700X75 (ASPH) S-30 MIRL 1.2% up E
RWY 07: PAPI(P2L)—GA 3.0° TCH 21'. Hlrd dsplcd 200'. Hill.
RWY 25: PAPI(P2L)—GA 3.5° TCH 34'. Hill.

SERVICE: S4 **FUEL** 100LL, JET A, A1 **OX** 1, 2, 3, 4 **LGT** Rwy 25 PAPI unusable byd 5° left of centerline. **ACTIVATE** PAPI Rwy 07, MIRL Rwy 07-25—CTAF. PAPI Rwy 25 opr continuously..

NOISE: Noise abatement Rwy 07: Track 070 straight out. Avoid turns prior to I-80 or 2500 MSL. Noise abatement Rwy 25: No straight out VFR dep. At end of rwy track 230 over self-storage fac to avoid noise sensitive areas. See noise abatement brochure:
www.auburn.ca.gov/510/noise-abatement.

AIRPORT REMARKS: Attended 1600-0200Z+. Fuel 100LL and Jet A avbl 24 hrs. Ultralight activity on and invof arpt. Helicopter TPA-2118(580). Helicopter rgt tfc for Rwy 07. Clsd tfc comply with aim proc. Min pwr while obsg safe acft ops.

AIRPORT MANAGER: 530-888-8174

WEATHER DATA SOURCES: AWOS-3 119.375 (530) 888-8934.

COMMUNICATIONS: CTAF/UNICOM 122.7

® **NORCAL APP/DEP CON** 125.4

CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-6874.

RADIO AIDS TO NAVIGATION: NOTAM FILE TVL.


PALISADES (VL) (DH) VORW/DME 113.2 SWR Chan 79 N39°10.82' W120°16.18' 235° 40.3 NM to fld.
8850/16E.

VOR unusable:

036°-048° byd 40 NM

112°-124° byd 40 NM blo 14,000'

112°-124° byd 53 NM



AVALON

CATALINA (AVX)(KAVX) 6 NW UTC-8(-7DT) N33°24.30' W118°24.95'
1602 NOTAM FILE AVX

RWY 04-22: H3000X75 (CONC) MIRL 1.8% up SW

RWY 22: REIL. PVASI(P2L)—GA 3.0° TCH 39'. Rgt tfc.

SERVICE: **LGT** ACTVT REIL Rwy 22—CTAF. PSIL Rwy 22 opr drg arpt operg hrs. Rwy 04-22 MIRL OTS indefly.

AIRPORT REMARKS: Attended 1600-0100Z+. Arpt CLOSED Thanksgiving and Christmas to all tntst tfc. Ops prohibited at night or when arpt is unatndd. No jet acft ops auth. Rwy 04-22 ltd by arpt opr to 12500 lbs mtow. Full stop ldg only; intxn tkofs prohibited. Rwy 04 final 2300 ft steep 2.1% downslope; Rwy 22 upslope preferred ldg. Pilots cannot see acft on opposite ends of rwy due to gradient, must annnc taking active rwy on unicom prior to dep. Rwy 04-22 NSTD rwy safety areas. Ldg fee.

AIRPORT MANAGER: 310-510-0143

WEATHER DATA SOURCES: ASOS 120.675 (310) 510-9641.

COMMUNICATIONS: CTAF/UNICOM 122.7

® **SOCAL APP/DEP CON** 127.4

CLEARANCE DELIVERY PHONE: For CD ctc SoCal Apch at 800-448-3724.

RADIO AIDS TO NAVIGATION: NOTAM FILE HHR.

SANTA CATALINA (L) (L) VORTACW 114.15 SXC Chan 88(Y)
N33°22.50' W118°25.19' 352° 1.8 NM to fld. 2090/15E.

VOR unusable:


314°-360° byd 25 NM

TACAN AZIMUTH unusable:

314°-360° byd 25 NM

DME unusable:

314°-360° byd 25 NM



LOS ANGELES

L-3E, 4G

IAP