

WAAS

CH **82738**

W30A

APP CRS

308°

Rwy Idg

4652

TDZE

2706

Apt Elev

2706

RNAV (GPS) RWY 30

HETTINGER/JB LINDQUIST RGNL (HEI)

⚠

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -20°C (-4°F) or above 54°C (130°F). DME/DME RNP-0.3 NA. Circling NA northeast of Rwy 12-30. Circling NA to Rwys 17 and 35.

MISSED APPROACH:

Climb to 6000 direct HAYNI and hold, continue climb-in-hold to 6000.

ASOS 119.925	MINNEAPOLIS CENTER 124.25 236.825	UNICOM 122.8 (CTAF) 1
------------------------	---	---------------------------------

3549

HAYNI

6 NM

175°

355°

5000 to IBOXE

127°

[22]

3313

3393

2915

3269

2703

RW30

2976

(FAF) KAKUH

4300

308°

(IF/IAF) IBOXE

128°

5 NM

MSA RW30 25 NM

4600

ELEV 2706

TDZE 2706

JELRO

5000

068°

(17.1)

6000 HAYNI		VGSi and RNAV glidepath not coincident (VGSi Angle 3.00/TCH 25).			
*LNAV only		IBOXE 5 NM Holding Pattern			
*1.7 NM to RW30		KAKUH 4300			
RW30		128° 5000			
1.7 NM		308° 4300			
3.2 NM		GP 3.00° TCH 40			
6 NM					
CATEGORY	A	B	C	D	
LPV DA	2956-1		250 (300-1)		
LNAV/VNAV DA	3233-1½		527 (600-1½)		
LNAV MDA	3260-1	554 (600-1)	3260-1½	554 (600-1½)	
CIRCLING	3260-1	554 (600-1)	3260-1½	3460-2½	554 (600-1½) 754 (800-2½)

HETTINGER, NORTH DAKOTA

Amdt 1 26MAY16

46°01'N-102°39'W

HETTINGER/JB LINDQUIST RGNL (HEI)

RNAV (GPS) RWY 30