

SCRIBNER STATE (SCB)(KSCB) 3 SE UTC-6(-5DT) N41°36.62' W96°37.79'

OMAHA
L-121
IAP

1325 B NOTAM FILE OLU
RWY 17-35: H4200X75 (CONC) S-25 MIRL
RWY 12-30: H3199X60 (CONC)
RWY 30: Thld dspld 399'.

SERVICE: FUEL 100LL LGT Apt bcn sked: rotg bcn ots indef. Bcn SS-SR. Windsock temply not lgtd.

AIRPORT REMARKS: Attended Mon-Fri 1330-2200Z. Rwy 12-30 has high severity linear cracks throughout. 100LL: Ctc amgt for fuel. Cash or ck only.

AIRPORT MANAGER: 402-480-2434

COMMUNICATIONS: CTAF 122.9


Ⓡ OMAHA APP/DEP CON 120.1

CLEARANCE DELIVERY PHONE: For CD ctc Omaha Apch at 402-682-4395.

RADIO AIDS TO NAVIGATION: NOTAM FILE LNK.

LINCOLN (VH) (H) VORTACW 116.1 LNK Chan 108 N40°55.43' W96°44.52' 358° 41.5 NM to fld. 1370/9E.

(T) (T) VOR/DME 111.0 SCB Chan 47 N41°36.29' W96°37.73' at fld. 1318/6E. NOTAM FILE OLU. VOR unmonitored.



SEARLE FLD (See OGALLALA on page 318)

SEWARD MUNI (SWT)(KSWT) 3 S UTC-6(-5DT) N40°51.88' W97°06.55'

OMAHA
L-101
IAP

1506 B NOTAM FILE OLU
RWY 16-34: H4200X75 (CONC) S-30, D-45, 2D-90 MIRL
0.3% up S

RWY 16: PAPI(P2L)—GA 3.0° TCH 41'. Road.

RWY 34: PAPI(P2L)—GA 3.0° TCH 41'. Road.

RWY 04-22: 3400X150 (TURF) 0.3% up SW
RWY 04: Tree.

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 16-34; PAPI Rwy 16 and Rwy 34; windsock—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1400-2300Z. Fuel self svc avbl 24 hrs. NOTE: See Special Notices Section—Aerobatic Practice Areas.

AIRPORT MANAGER: 402-643-2125

COMMUNICATIONS: CTAF/UNICOM 122.8

LINCOLN RCO 122.65 (COLUMBUS RADIO)

Ⓡ OMAHA APP/DEP CON 124.0

CLEARANCE DELIVERY PHONE: For CD ctc Omaha Apch at 402-682-4395.

RADIO AIDS TO NAVIGATION: NOTAM FILE LNK.

LINCOLN (VH) (H) VORTACW 116.1 LNK Chan 108 N40°55.43' W96°44.52' 249° 17.1 NM to fld. 1370/9E.

