

LYNDEN MUNI/JANSEN FLD (38W) 1 N UTC-8(-7DT) N48°57.35' W122°27.49' SEATTLE
 106 B NOTAM FILE SEA
RWY 08-26: H2425X40 (ASPH) S-12 RWY LGTS(NSTD)
RWY 08: PAPI(P2L)—GA 3.0° TCH 15'. Thld dsplcd 262'. Trees.
RWY 26: PAPI(P2R)—GA 6.0° TCH 15'. Thld dsplcd 422'. Trees.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 08: LDA-2163
RWY 26: TORA-2425 LDA-2003
SERVICE: FUEL 100LL LGT Use 3 clicks to ACTVT MIRL Rwy 08-26 and rotating bcn—CTAF.
AIRPORT REMARKS: Unattended. Automated credit card system for fuel. Exposed ditch Rwy 08-26. Avoid night lndgs to Rwy 26—night lndgs should be performed on Rwy 08—winds permitting. 1850 ft btn thr lgts; Rwy 08 thr lgts located 134 ft prior to dsplcd thr. Rwy 08 thr relctd 155 ft for ngt opns; Rwy 26 thr relctd 434 ft for ngt opns; 1871 ft lgtd at night. No white/red lgts past dsplcd thld. Run-ups not permitted on Rwy 26 turn around taxiway. Fly PAPI on all approaches to Rwy 08. WSDOT kiosk lctd at fuel stn. Bicycles avbl in pilot's lounge.
AIRPORT MANAGER: 360-354-3446
COMMUNICATIONS: CTAF 122.9
VICTORIA TERMINAL APP/DEP CON 132.7 290.8 604-586-4560
COMM/NAV/WEATHER REMARKS: Automated UNICOM; 3 clicks.

MANSFIELD (8W3) 0 E UTC-8(-7DT) N47°48.56' W119°38.22' SEATTLE
 2272 B NOTAM FILE SEA
RWY 03-21: H2575X46 (ASPH) LIRL
RWY 03: Road.
RWY 21: Road.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 03: TORA-2400
RWY 21: TORA-2400
SERVICE: LGT Rwy 03-21 no rwy lgts northside of Rwy 21 end to midfield. Bcn tempo OTS.
AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 has widespread, open unsealed cracks and joints. NW prkg has steep dropoff. Rwy 03-21 markings faded. Pilots bring own ropes. Lgtd wind tee.
AIRPORT MANAGER: 509-884-4700
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

MARTIN FLD (See COLLEGE PLACE on page 227)

MATTAWA

DESERT AIRE RGNL (M94) 3 SW UTC-8(-7DT) N46°41.24' W119°55.18' SEATTLE
 586 B NOTAM FILE SEA
RWY 10-28: H3665X60 (ASPH) MIRL
RWY 10: Bldg.
RWY 28: PAPI(P2L)—GA 4.0° TCH 45'.
SERVICE: LGT ACTVT MIRL Rwy 10-28—CTAF 5 mic clicks. ACTVT rotg bcn—CTAF 7 mic clicks.
AIRPORT REMARKS: Unattended. No touch and go ldgs prior to 1600Z±. Long final and extd base apchs to Rwy 28 not advised due to close proximity of low flying fast mil jets. Tran parking lctd on southeast and southwest end of arpt. EMS helicopter parking area on southwest end of arpt. Twy marked with retro-reflective devices. Pavement rated for 18,000 lbs aircraft.
AIRPORT MANAGER: 509-596-2298
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2525, when Apch clsd ctc Seattle ARTCC at 253-351-3694.
RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.
MOSES LAKE (VH) (DH) VORW/DME 115.0 MWH Chan 97 N47°12.65' W119°19.01' 200° 40.0 NM to fld.
 1193/18E.
 VOR unusable:
 025°-040° byd 40 NM
 055°-070° byd 40 NM
 071°-081° byd 40 NM blo 28,000'
 175°-198° byd 40 NM blo 6,000'
 175°-198° byd 67 NM blo 10,000'
 175°-198° byd 70 NM
 200°-210° byd 40 NM
 220°-230° byd 40 NM
 240°-253° byd 40 NM blo 18,000'
 254°-260° byd 40 NM
 315°-345° byd 40 NM
COMM/NAV/WEATHER REMARKS: Lcl wx adzy avbl—CTAF 3 mic clicks.