

**AKRON-CANTON RGNL** (CAK)(KCAK) P (ARNG) 10 SE UTC-5(-4DT) N40°54.90' W81°26.62'

DETROIT

1226 B LRA ARFF Index—See Remarks NOTAM FILE CAK MON Airport

H-10G, L-29B

**RWY 05-23:** H8204X150 (ASPH-GRVD) S-120, D-160, 2S-175,

IAP, AD

2D-250 PCN 133F/C/X/T HIRL

**RWY 05:** MALSR. PAPI(P4L)—GA 3.0° TCH 50'. RVR-TR 0.5% up.

**RWY 23:** MALSR. PAPI(P4L)—GA 3.0° TCH 47'. RVR-TR 0.6% down.

**RWY 01-19:** H7601X150 (ASPH-GRVD) S-120, D-160, 2S-175,

2D-250 PCN 85 F/C/X/T HIRL

**RWY 01:** MALSR. RVR-TR

**RWY 19:** MALSR. PAPI(P4L)—GA 3.0° TCH 53'. RVR-TR Thld dspcd 601'.

**LAND AND HOLD—SHORT OPERATIONS**

LDG RWY	HOLD—SHORT POINT	AVBL LDG DIST
RWY 05	01-19	5723
RWY 19	05-23	3100

**RUNWAY DECLARED DISTANCE INFORMATION**


**RWY 01:** TORA-7601 TODA-7601 ASDA-7007 LDA-7007

**RWY 05:** TORA-8204 TODA-8204 ASDA-8204 LDA-8204

**RWY 19:** TORA-7601 TODA-7601 ASDA-7601 LDA-7007

**RWY 23:** TORA-8204 TODA-8204 ASDA-8204 LDA-8204

**SERVICE:** S4 FUEL 100LL, JET A OX 1, 2 MILITARY— FUEL A, A+ (C330-494-6104) (NC-100LL).



**AIRPORT REMARKS:** Attended continuously. All acft taxiing on Air Camis

Ramp and north hangar areas not visible from twr. Deer and birds on and in/ov arpt. Class I, ARFF Index B, ARFF svc not avbl 0100-0500 local (0600-1000Z±) daily. One hour PPR for unsked air carrier ops, call arpt manager 330-499-4059. Twy E east of Twy B clsd to acft over 118' wingspan. Non-commercial landing fee: multi-engine only. Flight Notification Service (ADCUS) avbl.

**AIRPORT MANAGER:** 330-754-5233

**WEATHER DATA SOURCES:** ASOS (330) 493-5260

**COMMUNICATIONS:** ATIS 121.05 UNICOM 122.95

Ⓡ CLEVELAND APP/DEP CON 118.6 (187°-006°) 125.5 (007°-186°) (1100-0600Z±)

Ⓡ CLEVELAND CENTER APP/DEP CON 134.9 (0600-1100Z±) ctc Cleveland ARTCC at 440-774-0223.

**TOWER** 134.75 **GND CON** 121.7 **CLNC DEL** 132.05

**ARNG OPS** 40.1 138.55 226.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0223.

**AIRSPACE:** CLASS C svc ctc APP CON svc 1100-0600Z±; other times CLASS D.

**VOR TEST FACILITY (VOT)** 110.6

**RADIO AIDS TO NAVIGATION:** NOTAM FILE CAK.

(L) (L) VORW/DME 114.4 ACO Chan 91 N41°06.47' W81°12.09' 228° 16.0 NM to fld. 1197/4W.

DME unusable:

Byd 10 NM

ILS 109.5 I-CAK Rwy 01. Class IA.

ILS/DME 108.3 I-EQX Chan 20 Rwy 05. Class IE.

ILS 109.5 I-RGO Rwy 19. Class IE.

ILS/DME 108.3 I-GGZ Chan 20 Rwy 23. Class IE. DME unusable byd 3° r of course.

**MAYFIELD** (1D4) 5 SE UTC-5(-4DT) N40°59.55' W81°25.91'

DETROIT

1100 NOTAM FILE CLE

**RWY 09-27:** 2315X110 (TURF) 0.3% up E

**RWY 09:** Thld dspcd 180'. Trees.

**RWY 27:** Thld dspcd 590'. Trees. Rgt tfc.

**AIRPORT REMARKS:** Attended irregularly. Deer, birds, and wildlife on and in/ov airport. Rwy 09-27 rolling trm, Rwy 27 upslope W end 12' higher than E end. Open to the public, wx and conds pmtg, ldg fees. No prkg, fees may apply. No UAS, or similar acft pmtd. No unauthorized vehicles, no trespassing. Rwy 09-27 mxd with tires at rwy end and dthr only.

**AIRPORT MANAGER:** 330-699-3066

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223.

**ALDERMAN** (See ST CLAIRSVILLE on page 313)

**ALEXANDER SALAMON** (See WEST UNION on page 326)