

MEADOW BROOK FLD (See WALNUT COVE on page 357)

MEYERS HELIPORT (See CANDLER on page 299)

MICHAEL J SMITH FLD (See BEAUFORT on page 297)

MID-CAROLINA RGNL (See SALISBURY on page 347)

MOCKSVILLE

TWIN LAKES (8A7) 5 NE UTC-5(-4DT) N35°54.89' W80°27.41'

818 B NOTAM FILE RDU

RWY 09-27: H2943X50 (ASPH) S-12.5 RWY LGTS(NSTD)

1.5% up E

RWY 09: PAPI(P2L)—GA 3.5' TCH 49'. Trees.

RWY 27: Trees.

SERVICE: S4 FUEL 100LL OX 4 LGT Rwy 09-27 nstd lighting due to number and location.

AIRPORT REMARKS: Attended 1300-2200Z±. Deer/migratory birds occasionally on arpt. For after hrs svc ctc 336-998-2126. 100LL 24 hr self service with credit card. Rwy 09 18' drop-off 150' from thld left and right of centerline. Rwy 09 uphill grade. Rwy 09-27 markings nonstandard due to size and location.

AIRPORT MANAGER: 336-998-8101

COMMUNICATIONS: CTAF/UNICOM 122.7

® **GREENSBORO APP/DEP CON** 124.35

CLEARANCE DELIVERY PHONE: For CD ctc Greensboro Apch at 336-333-5119.

RADIO AIDS TO NAVIGATION: NOTAM FILE GSO.

GREENSBORO (VH) (H) VORTAC 116.2 GSO Chan 109 N36°02.74' W79°58.58' 255° 24.7 NM to fld. 908/3W.

TACAN AZIMUTH unusable:
255°-290° byd 10 NM blo 6,000'

VOR unusable:

010°-015° byd 40 NM
072°-076° byd 40 NM
083°-093° byd 40 NM blo 6,000'
083°-093° byd 93 NM
107°-111° byd 40 NM
118°-156° byd 40 NM
157°-167° byd 40 NM blo 3,600'
157°-167° byd 48 NM
168°-180° byd 40 NM
196°-199° byd 40 NM
240°-250° byd 40 NM
260°-276° byd 40 NM
277°-288° byd 40 NM blo 3,500'
277°-288° byd 47 NM blo 6,000'
277°-288° byd 56 NM
289°-302° byd 40 NM blo 5,000'
289°-302° byd 55 NM
303°-317° byd 40 NM blo 5,200'
303°-317° byd 55 NM
318°-354° byd 40 NM

CHARLOTTE

L-25D, 36F

IAP

