MINNESOTA

CONTINUED FROM PRECEDING PAGE

```
WEATHER DATA SOURCES: ASOS 120.0 (218) 285-6156.
        COMMUNICATIONS: CTAF/UNICOM 122.8
          INTERNATIONAL FALLS RC0 122.6 (PRINCETON RADIO)
       ® MINNEAPOLIS CENTER APP/DEP CON 120.9
        CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Minneapolis ARTCC at 651-463-5588.
        A ID - FOAD
        RADIO AIDS TO NAVIGATION: NOTAM FILE INL.
          INTERNATIONAL FALLS (VL) (DH) VORW/DME 114.95 INL Chan 96(Y) N48°33.95′ W93°24.34′ at fld, 1180/6E.
          VOR unusable-
            164°-169° byd 40 NM
            170°-178° byd 35 NM blo 5,000'
            170º-185º blo 4,000
            179°-185° byd 35 NM
            225°-265° byd 15 NM
            285°-290°
            310°-351° byd 13 NM blo 4,000 '
          DME unusable:
            260°-269° byd 15 NM blo 4,000 7
            270°-275° byd 30 NM blo 3,000'
          ILS 109.1 I-ABK Rwy 13. Class IB. Unmonitored.
          ILS 111.95 I-INL Rwy 31. Class IA. LOC unusable wi 0.2 NM inbd. LOC unusable byd 26° left and right of course.
            Autopilot cpd apch NA blw 1,731'.
               INTL FALLS SPB (Ø9I) 1 E UTC-6(-5DT) N48°36.35' W93°22.25'
                                                                                                         TWIN CITIFS
        1110 TPA-1710(600) AOE NOTAM FILE PNM
        WATERWAY 05W-23W: 5000X1000 (WATER)
        WATERWAY 08W-26W: 5000X1000 (WATER)
        SERVICE: FILE 10011
        SEAPLANE REMARKS: Unattended. Unicom located at Falls Intl-Einarson Fld. Acft requiring U.S. Customs ctc Princeton FSS on
          123.6 15 minutes prior to arr also call U.S. Customs at 218-283-2541 prior to tkf. Pilots ctc Falls Intl-Einarson Fld on
          122.8 for aeronautical advisory information for the seaplane base. Phone located in customs building. Pilots maintain
          500'AGL TPA separation from tfc at Falls Intl-Einarson Fld arpt 2 miles southwest. For fuel call on 122.8 or
          218-283-4461. Use caution for a + 105 ' lookout twr north of facility on the Canadian side of the river. Windsock located
          at border patrol helipad approx 1/2 mile west of seaplane dock.
        AIRPORT MANAGER: 218-283-4461
        COMMUNICATIONS: CTAF/UNICOM 122.8
        CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.
     INTL FALLS SPB (See INTERNATIONAL FALLS on page 177)
INVER GROVE HGTS
     WIPLINE SPB (Ø9Y) 2 SE UTC-6(-5DT) N44°49.65' W93°00.52'
                                                                                                         TWIN CITIES
        687 NOTAM FILE PNM
        WATERWAY 17W-35W: 8000X500 (WATER)
          WATERWAY 35W: Rgt tfc.
        SERVICE: S2 FUEL 100LL
        SEAPLANE REMARKS: Attended continuously, 100LL; For fuel call amgr. Floating debris on river at all times. River channel
          marked by buoys.
        AIRPORT MANAGER: 612-286-6612
```

ISEDOR IVERSON (See MC GREGOR on page 185)

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

COMMUNICATIONS: CTAF 122.9