NEW YORK

251

UTICA/FRANKFORT FRANKFORT-HIGHLAND (6B4) 4 SE UTC-5(-4DT) N43°00.97 1325 NOTAM FILE BUF RWY13-31: H2750X60 (ASPH) S-12 LIRL 0.4% up NW RWY13: Thild dsplcd 200'. Trees. RWY31: Thild dsplcd 205'. SERVICE: FUEL 100LL AIRPORT REMARKS: Unattended. Geese on and invof arpt during spring and fuel. Rwy 31 has 120' dropoff 90' from thid, both sides. LIRL Rwy AIRPORT MANAGER: 315-796-6257 COMMUNICATIONS: CTAF/UNICOM 122.8 CLEARANCE DELIVERY PHONE: For CD ctc Syracuse Apch at 315-455-6218.	
UTICA N43°01.59´W75°09.87´ NOTAM FILE BUF. (L) TACAN 111.2 UCA Chan 49 319° 16.4 NM to Griffiss Intl. 1420 RCO 122.2 (BUFFALO RADIO)	NEW YOUR /OW. L-32G
WALLKILL KOBELT (N45) 2 NE UTC-5(-4DT) N41°37.45' W74°08.50' 420 B NOTAM FILE ISP RWY 03-21: H2864X50 (ASPH) S-13 RWY 03: Trees. RWY 21: Trees. AIRPORT REMARKS: Unattended. Arpt clsd to acft 13,500 lbs and over. De SFC-14,500'. Rwy 03 has access road 16' from thild both sides. Rw on both sides of centerline in poor condition with extensive cracks and areas opposite south end of rwy. Rwy center 30' in fair condition, out parallel twy, stub connectors to rwy between ends in poor condition. AIRPORT MANAGER: 914-548-3028 COMMUNICATIONS: CTAF/UNICOM 122.8 CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448	y center width of $30'$ in good condition, $10'$ width vegetation. Rwy $03-21$ slight depression in grass side edges beyond this in poor condition. $18'$ wide
WARWICK MUNI (N72) 3 NE UTC-5(-4DT) N41°17.26' W74' 540 NOTAM FILE ISP RWY 08-26: 2250X80 (TURF) RWY 08-26: 2250X80 (TURF) RWY 08-211: H2150X28 (ASPH) LIRL(NSTD) RWY 031-211: H2150X28 (ASPH) LIRL(NSTD) RWY 031-211: 2100X50 (TURF) RWY 031-211: 2100X50 (TU	sunrise. Deer and bird act near movement areas. 3 has 6´ chain link fence 58´ left, parallel to rwy.