

CONTINUED FROM PRECEDING PAGE

AIRPORT MANAGER: 814-793-2027

WEATHER DATA SOURCES: ASOS 127.125 (814) 793-9655.

COMMUNICATIONS: CTAF 123.6

RCO 122.2 (ALTOONA RADIO)

Ⓡ JOHNSTOWN APP/DEP CON 121.2 (1200-0400Z±)

Ⓡ CLEVELAND CENTER APP/DEP CON 124.4 (0400-1200Z±)

CLEARANCE DELIVERY PHONE: For CD ctc Johnstown Apch at 814-532-5960, when Apch clsd ctc Cleveland ARTCC at 440-774-0213.

AIRSPACE: CLASS E.

RADIO AIDS TO NAVIGATION: NOTAM FILE A00.

ST THOMAS (L) TACAN Chan 97 THS (115.0) N39°55.99' W77°57.06' 329° 27.6 NM to fld. 2338/7W.

ILS 111.1 I-A00 Rwy 21. Class IA. LOC unusable byd 25° right of course.

ARNOLD PALMER RGNL (See LATROBE on page 286)

BALLY

BUTTER VALLEY GOLF PORT (7N8) 1 E UTC-5(-4DT) N40°23.85' W75°33.79' NEW YORK

500 NOTAM FILE IPT

RWY 16-34: H2420X85 (ASPH-TURF)

RWY 16: Thld dsplcd 205'. Road.

RWY 34: Thld dsplcd 250'. Road.

AIRPORT REMARKS: Attended daylight hours. Rwy 16-34 located in middle of golf course. Trees and substantial terrain elevation changes within 125' of each rwy edge. Rwy 16-34 1535 ft X 24 ft asph insert at S end; remainder turf. Rwy 16 marked with yellow wood panels; turf rwy edges marked with tires painted yellow. Rwy 34 dsplcd thld marked with 3 white lines. Rwy 16 dsplcd thld marked by 3 yellow tires. Rwy 34: 119 ft tree line 1472 ft fm rwy end; 233 ft right. 12:1 slope to dthr.

AIRPORT MANAGER: 610-845-2491

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Allentown Apch at 800-728-6322.

BANDEL (See EIGHTY FOUR on page 272)

BAUBLITZ COMMERCIAL (See BROGUE on page 265)

BEAVER CO (See BEAVER FALLS on page 261)