

STAUNTON/WAYNESBORO/HARRISONBURG**SHENANDOAH VALLEY RGNL** (SHD)(KSHD) 10 NE UTC-5(-4DT) N38°15.83' W78°53.79'

WASHINGTON

1201 B TPA—See Remarks Class I, ARFF Index B NOTAM FILE SHD

H-10H, 12I, L-26J

RWY 05-23: H6002X150 (ASPH-GRVD) S-75, D-150, 2S-175, 2D-215 PCN 44 F/B/X/U HIRL

IAP, AD

0.4% up NE

RWY 05: MALSR. PAPI(P4L)—GA 3.0° TCH 56'. Pole.**RWY 23:** REIL. PAPI(P4L)—GA 3.0° TCH 44'.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 05:** TORA-6002 TODA-6002 ASDA-6002 LDA-6002**RWY 23:** TORA-6002 TODA-6002 ASDA-6002 LDA-6002**SERVICE:** S4 FUEL 100LL, JET A 0X3, 4 LGT Actvt MALSR Rwy 05; REIL Rwy 23; HIRL Rwy 05-23 & twy lgts—CTAF.

PAPI Rwy 05 and 23 oprs consly.

AIRPORT REMARKS: Attended continuously. PPR 12 hrs for unsked air carrier ops with more than 30 passenger seats call

540-234-8304. TPA 2001(800) piston acft, 2701(1500) jet/turbo acft.

AIRPORT MANAGER: 540-234-8304**WEATHER DATA SOURCES:** AWOS-3 124.925 (540) 234-0110.**COMMUNICATIONS:** CTAF/UNICOM 123.0**MONTEBELLO RCO** 122.1R 115.3T (LEESBURG RADIO)Ⓡ **POTOMAC APP/DEP CON** 132.85

CLNC DEL 118.35

CLEARANCE DELIVERY PHONE: For CD ctc Potomac Apch at 866-640-4124.**AIRSPACE:** CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.**MONTEBELLO (VL) (L) VOR/DME** 115.3 MOL Chan 100 N37°54.03' W79°06.41' 030° 23.9 NM to fld. 3455/5W.

DME unusable:

158°-168° byd 30 NM blo 6,000'

STAUT NDB (LOMW) 375 SH N38°12.11' W78°57.44' 047° 4.7 NM to fld. 1240/9W. NOTAM FILE SHD.**ILS** 109.5 I-SHD Rwy 05. Class IT. LOM STAUT NDB. Autopilot cpd apch NA blw 1,600' MSL. Unmonitored when

FBO clsd.

STAUT N38°12.11' W78°57.44' NOTAM FILE SHD.

CINCINNATI

NDB (LOMW) 375 SH 047° 4.7 NM to Shenandoah Valley Rgnl. 1240/9W.**SUFFOLK EXEC** (SFQ)(KSFQ) 3 SW UTC-5(-4DT) N36°40.97' W76°35.98'

WASHINGTON

70 B NOTAM FILE SFQ

H-10I, 12I, L-35D, 36H

RWY 04-22: H5007X100 (ASPH) S-30, D-60, 2D-60 HIRL

IAP

RWY 04: REIL. PAPI(P4L)—GA 3.0° TCH 39'. Tree. Rgt tfc.**RWY 22:** REIL. PAPI(P4L)—GA 3.5° TCH 45'. Trees.**RWY 07-25:** H3750X100 (ASPH) S-30, D-50, 2D-85 MIRL**RWY 07:** Tree.**RWY 25:** Trees. Rgt tfc.**SERVICE:** S4 FUEL 100LL, JET A, MOGAS LGT Actvt REIL Rwys 04 & 22; HIRL Rwy 04-22; MIRL Rwy 07-25—CTAF.**AIRPORT REMARKS:** Attended 1300-2200Z. Parachute Jumping. Deer on and invof arpt. Parachute activity on and invof arpt. Rwy 07 rwy end arrow heads painted white instead of designed aviation yellow. Rwy 07 markings faded and poor condition. Rwy 25 markings in poor condition.**AIRPORT MANAGER:** 757-514-4411**WEATHER DATA SOURCES:** AWOS-3 119.375 (757) 934-3942.**COMMUNICATIONS:** CTAF/UNICOM 122.7Ⓡ **NORFOLK APP/DEP CON** 127.9**CLEARANCE DELIVERY PHONE:** For CD ctc Norfolk Apch at 757-464-0757.**RADIO AIDS TO NAVIGATION:** NOTAM FILE FKN.**FRANKLIN (L) (L) VORTACW** 110.6 FKN Chan 43 N36°42.85'

W77°00.74' 104° 20.0 NM to fld. 84/9W.

VOR unusable:

090°-119° byd 18 NM blo 2,000'

119°-128° byd 10 NM

129°-134° byd 33 NM

135°-148°

TACAN AZIMUTH unusable:

090°-139°

DME unusable:

090°-139°

LOC/DME 109.95 I-RKH Chan 36(Y) Rwy 04.