
LUCKY LANDING MARINA SPB (See BANGOR on page 60)



MEDDYBEMPS

 GILLESPIE FLD
 (66B)
 1 W
 UTC-5(-4DT)
 N45°01.78' W67°21.96'
 HALIFAX

 200
 NOTAM FILE BGR
 RWY 16-34: 1635X50 (TURF)
 RWY 16-34: 1635X50 (TURF)
 RWY 36: Trees.

 RWY 16: Trees.
 RWY 34: Trees.
 RWY 34: Trees.
 RWY 16-34 temporarily CLOSED and not being mntnd. Rwy not plowed winter months. 36'

 pwr In 280' N of Rwy 16 mkd with balls.
 AIRPORT MANAGER: 603-726-6587
 COMMUNICATIONS: CTAF 122.9

 CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.
 CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

MERRYMEETING FLD (See BOWDOINHAM on page 62)

MILLINOCKET

 MILLINOCKET SPB
 (7ØB)
 7 NW
 UTC-5(-4DT)
 N45°43.70′ W68°50.67′
 HALIFAX

 492
 NOTAM FILE BGR
 WATERWAY ALL-WAY: 4000X500 (WATER)
 SERVICE: FUEL 100LL
 SERVICE: FUEL 100LL

 SEAPLANE REMARKS: Attended May–Oct dawn-dusk. Arpt clsd 31 Oct through 30 Apr. Water level fluctuates 10′ +/- lowest in Sep and Oct. Preferred tkf and ldg direction for SPB Rwy 04–22. Significant amount of boat activity sharing sea lanes. Buoys have been added to identify rocks at low water levels. Location of buoys rqr tkf and ldg direction of Rwy 04–22 with buoys at outer edges of sea lane. Unlighted 199′ cell twr located 2 SM at 132° from dock. Twr underlies downwind to baseleg of pattern when ldg to the southwest.

 AIRPORT MANAGER: 207-723-8378
 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.