## OREGON

| OWYHEE RESERVOIR STATE (28U)<br>2680 NOTAM FILE MMV<br>RWY 13-31: 1840X30 (DIRT)<br>AIRPORT REMARKS: Unattended. Owner<br>arpt, no ground access. Arpt in can<br>irregular maintenance. Rwy surface<br>AIRPORT MANAGER: 503-378-4880<br>COMMUNICATIONS: CTAF 122.9<br>CLEARANCE DELIVERY PHONE: For CD ctc :  | advises ctc with State De<br>yon, surrounded by high to<br>e frequently rough and rut | partment of Aviation 503–378–488<br>errain. 4´ brush growth within 20´ o<br>ted. Sur conds not rprtd. |                        |
|---|---|---|------------------------|
| <ul> <li>PACIFIC CITY STATE (PFC)(KPFC) 1 S UTC-8(-7DT) N45°11.96' W123°57.71' SEATTLE 10 NOTAM FILE MMV</li> <li>RWY 14-32: H1860X30 (ASPH) S-7</li> <li>RWY 14-32: H1860X30 (ASPH) S-7</li> <li>RWY 14-Tree.</li> <li>AIRPORT REMARKS: Unattended. Owner advises ctc with Department of Aviation 503–378–4880 prior to use. Rwy may be under water dur winter high tides. Ocnl driftwood on rwy due to flooding. Sfc conds not rprtd. Downwind ldgs not recommended and may not be possible. Many close in obst on both sides of rwy. Exp low level turbulence dur crosswind cond. Assorted trees and 40' p–line at 500' north of rwy. Pre-tkof engine run–ups to be conducted at the parking ramp only.</li> <li>AIRPORT MANAGER: 503-378-4880</li> <li>COMMUNICATIONS: CTAF 122.9</li> <li>CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.</li> </ul> |   |   |                        |
| PAISLEY (22S) 3 NW UTC-8(-7<br>4395 B NOTAM FILE MMV<br>RWY 13-31: H4300X60 (ASPH) LI<br>AIRPORT REMARKS: Unattended. Rwy 13<br>AIRPORT MANAGER: 541-947-4222<br>COMMUNICATIONS: CTAF 122.9<br>CLEARANCE DELIVERY PHONE: For CD ctc :<br>RADIO AIDS TO NAVIGATION: NOTAM FILE   | RL 0.4% up SE<br>3 has aiming points.<br>Seattle ARTCC at 253-35                      |   | KLAMATH FALLS<br>L-11A |

UDIO AIUS TO NAVIGATION: NOTAM FILE LKV. LAKEVIEW (H) (H) VORTACW 112.0 LKV Chan 57 N42°29.57′W120°30.43′ 331°13.7 NM to fld. 7465/19E.

\_