

TUCUMCARI MUNI (TCC)(KTCC) 6 E UTC-7(-6DT) N35°10.97' W103°36.19'

ALBUQUERQUE

4065 B NOTAM FILE TCC MON Airport

H-6G, L-15A

RWY 03-21: H7104X100 (ASPH) S-25 PCN 10 F/C/Y/T MIRL

IAP

RWY 21: VASI(V4L)—GA 3.0° TCH 52'.

RWY 08-26: H4600X60 (ASPH) S-12 PCN 6 F/D/Y/T MIRL

0.6% up W

SERVICE: FUEL 100LL, JET A+ LGT ACTVT VASI Rwy 21; MIRL Rwy 03-21 and Rwy 08-26—CTAF.

AIRPORT REMARKS: Attended 1400-0000Z†, clsd fed hol. Aft hr fuel self svc with credit card.

AIRPORT MANAGER: 575-461-3229

WEATHER DATA SOURCES: ASOS 119.275 (575) 461-4940.

COMMUNICATIONS: CTAF/UNICOM 122.95

RCO 122.4 (ALBUQUERQUE RADIO)

Ⓡ ALBUQUERQUE CENTER APP/DEP CON 126.85

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Albuquerque ARTCC at 505-856-4561.

AIRSPACE: CLASS E svc 1500-2300Z†; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE TCC.

(VH) (H) VORTACW 113.6 TCC Chan 83 N35°10.93'

W103°35.91' at fld. 4035/12E.

VOR unusable:

125°-174° byd 40 NM

175°-193° byd 40 NM blo 12,500'

194°-227° byd 40 NM

228°-238° byd 40 NM blo 11,000'

228°-238° byd 46 NM

239°-249° byd 40 NM

250°-261° byd 40 NM blo 7,700'

250°-261° byd 46 NM blo 18,000'

262°-273° byd 40 NM

274°-284° byd 40 NM blo 18,000'

285°-355° byd 40 NM

