

MADISON**BLACKHAWK AIRFIELD** (87Y) 10 E UTC-6(-5DT) N43°06.28' W89°11.12'**CHICAGO**

920 B NOTAM FILE GRB

L-28H

RWY 04-22: H2814X57 (ASPH) 0.5% up SW

IAP

RWY 04: Trees. Rgt tfc.**RWY 22:** Thld dsplcd 260'. Trees.**RWY 09-27:** H2203X56 (ASPH) LIRL(NSTD) 0.7% up W**RWY 09:** Road.**RWY 27:** Thld dsplcd 230'. Road. Rgt tfc.**SERVICE:** LGT Rwy 09-27 nstd LIRL; Rwy lgts 2' to 3' above rwy and nstd spacing. Rwy 09-27 lgtd 1973'.**AIRPORT REMARKS:** Unattended. Deer and turkeys on and invof arpt. Rwy 09 avoid overflight of farm 3/4 mile east. Rwy ends obstructed visually from others. Rwy 04-22 cracks with vegetation. Rwy 04-22 and Rwy 09-27 markings faded. Cold temperature airport. Altitude correction required at or below -24C.**AIRPORT MANAGER:** (608) 334-4932**COMMUNICATIONS:** CTAF/UNICOM 122.7Ⓡ **MADISON APP/DEP CON** 120.1 (1200-0500Z±)Ⓡ **CHICAGO CENTER APP/DEP CON** 133.3 (Hours Madison apch clsd)**CLEARANCE DELIVERY PHONE:** For CD ctc Madison app/dep con at 608-249-8240. When Madison Apch clsd, for CD ctc Chicago ARTCC at 630-906-8921.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MSN.**MADISON (L) VORTACW** 108.6 MSN Chan 23 N43°08.69' W89°20.38' 106° 7.2 NM to fld. 857/3E.

mnrtd by twr

TACAN AZIMUTH & DME unusable:

010°-070° byd 20 NM blo 4,500'

070°-210° byd 20 NM blo 3,500'

210°-240° byd 30 NM blo 4,000'

285°-010° byd 30 NM blo 4,000'

VOR portion unusable:

155°-230° byd 20 NM blo 2,800'

230°-155° byd 30 NM blo 2,800'

TACAN AZIMUTH unusable:

240°-285° byd 9 NM

TACAN DME unusable:

240°-285° byd 30 NM blo 4,000'