

STAATSBURG**AIRHAVEN** (Ø9N) 3 SE UTC-5(-4DT) N41°49.96' W73°52.57'

NEW YORK

450 NOTAM FILE ISP

RWY 02-20: 1863X75 (TURF) 1.5% up N**RWY 02:** Tree.**RWY 20:** Trees.**AIRPORT REMARKS:** Unattended. Rwy not plowed in winter. Rwy 02-20 2' pvc reflective markers, blue markers at thld, all others along edges are white. Rwy 20 has +50' trees, 30' from thld, 50' left. Steep grades and drop-offs located in Rwy 02 safety area.**AIRPORT MANAGER:** 845-889-4717**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc New York Apch at 516-683-2448.**STORMVILLE** (N69) 1 NE UTC-5(-4DT) N41°34.62' W73°43.94'

NEW YORK


358 NOTAM FILE ISP

RWY 06-24: H3315X50 (ASPH) S-25 0.8% up NE**RWY 06:** Trees.**AIRPORT REMARKS:** Unattended. Geese on and invof rwy. Rwy 06-24 not plowed. Flee market obstns and material may be next to rwy ends. Rwy 06-24 wide cracks and weeds on rwy.**AIRPORT MANAGER:** (845) 227-4444**COMMUNICATIONS:** CTAF/UNICOM 122.8

Ⓡ NEW YORK APP/DEP CON 132.75

CLEARANCE DELIVERY PHONE: For CD ctc New York Apch at 516-683-2448.

L-33B, 34I

**SUFFOLK CO** N40°50.27' W72°37.91' NOTAM FILE FOK.

NEW YORK

(T) TACAN 111.0 FOK Chan 47 at Francis S Gabreski. 50/13W. TACAN unmonitored when twr clsd.

L-33B, 34I

No NOTAM MP: 1600-2000Z‡ Mon

TACAN AZIMUTH unusable:

028°-038° byd 8 NM blo 3,500'

090°-155° byd 7 NM

335°-345° byd 7 NM blo 3,500'

SULLIVAN CO INTL (See MONTICELLO on page 224)