

RAVALLI CO (See HAMILTON on page 114)

RED LODGE (RED)(KRED) 1 NW UTC-7(-6DT) N45°11.09' W109°15.46'
5762 B NOTAM FILE GTF

RWY 16-34: H4000X75 (ASPH) S-4, D-6 MIRL 1.6% up S

RWY 16: VASI(V2L)—GA 3.0° TCH 27'. Tree.

RWY 34: Road.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 16-34 and VASI Rwy 16—CTAF.

AIRPORT REMARKS: Unattended. Wildlife on and invof rwy. 24 hr credit card 100LL. New card reader for fuel. Pavement cracking and eroding at edges, loose grvl on rwy sfc. Rwy 16 mrkgs faded and msg sections. Rwy 34 mrkgs faded.

AIRPORT MANAGER: 406-425-3143

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE BIL.

BILLINGS (VH) (H) VORTACW 114.5 BIL Chan 92 N45°48.51'
W108°37.48' 202° 46.0 NM to fld. 3811/14E.

VOR unusable:


146°-154° byd 40 NM

155°-165° byd 40 NM blo 11,000'

155°-165° byd 49 NM blo 18,000'

166°-173° byd 40 NM

GREAT FALLS
L-13D



RICHEY (7U8) 1 SW UTC-7(-6DT) N47°37.59' W105°04.78'
2494 NOTAM FILE GTF

RWY 14-32: 2690X75 (TURF-DIRT)

RWY 32: Hill.

AIRPORT REMARKS: Unattended. AER 14 has dip obscured by grass prior to thld. No snow removal.

AIRPORT MANAGER: 406-444-2506

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

BILLINGS

RIDDICK FLD (See PHILIPSBURG on page 131)

ROCK CREEK (See CLINTON on page 100)