

LOPEZ

FISHERMANS BAY SPB (81W) 1 N UTC-8(-7DT) N48°30.99' W122°55.08' SEATTLE
 00 NOTAM FILE SEA
WATERWAY 05W-23W: 3000X150 (WATER)
WATERWAY 05W: Rgt tfc.
SEAPLANE REMARKS: Unattended. Avoid overflights of houses on surrounding land. No step taxi in bay. Beware of boats anchored in seaplane ldg area.
AIRPORT MANAGER: 360-468-4116
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

LOPEZ ISLAND (S31) 3 N UTC-8(-7DT) N48°29.04' W122°56.26' SEATTLE
 209 B NOTAM FILE SEA
RWY 16-34: H2905X61 (ASPH-GRVD) S-12.5 MIRL 1.6% up N
RWY 16: REIL. PAPI(P2L)—GA 4.0° TCH 43'. Trees. Rgt tfc.
RWY 34: REIL. PAPI(P2L)—GA 4.0° TCH 33'. Trees.
AIRPORT REMARKS: Unattended. Rwy 16-34 soft shoulders and thlds.
AIRPORT MANAGER: 360-468-4116
COMMUNICATIONS: CTAF 128.25
CLEARANCE DELIVERY PHONE: For CD ctc Whidbey Apch at 360-257-3310.

LOST RIVER (See MAZAMA on page 249)

LOWER GRANITE STATE (See COLFAX on page 229)

LOWER MONUMENTAL STATE (See KAHLOTUS on page 243)

LYNDEN MUNI/JANSEN FLD (38W) 1 N UTC-8(-7DT) N48°57.35' W122°27.49' SEATTLE
 106 B NOTAM FILE SEA
RWY 08-26: H2425X40 (ASPH) S-12 RWY LGTS(NSTD)
RWY 08: PAPI(P2L)—GA 3.0° TCH 15'. Thld dsplcd 262'. Trees.
RWY 26: PAPI(P2R)—GA 6.0° TCH 15'. Thld dsplcd 422'. Trees.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 08: LDA-2163
RWY 26: TORA-2425 LDA-2003
SERVICE: FUEL 100LL LGT Use 3 clicks to ACTVT MIRL Rwy 08-26 and rotating bcn—CTAF.
AIRPORT REMARKS: Unattended. Automated credit card system for fuel. Structures and trees in pri sfc. Exposed ditch Rwy 08-26. Avoid night lndgs to Rwy 26—night lndgs should be performed on Rwy 08—winds permitting. 1850 ft btn thr lgts; Rwy 08 thr lgts located 134 ft prior to dsplcd thr. Rwy 08 thr relctd 155 ft for ngt opns; Rwy 26 thr relctd 434 ft for ngt opns; 1871 ft lgtd at night. No white/red lgts past dsplcd thld. Run-ups not permitted on Rwy 26 turn around taxiway. Acft with 40 ft wing span adzd to back taxi and not to use west twy. Fly PAPI on all approaches to Rwy 08. WSDOT kiosk lctd at fuel stn. Bicycles avbl in pilot's lounge.
AIRPORT MANAGER: 360-354-3446
COMMUNICATIONS: CTAF 122.9
VICTORIA TERMINAL APP/DEP CON 132.7 290.8 604-586-4560
COMM/NAV/WEATHER REMARKS: Automated UNICOM; 3 clicks.

MANSFIELD (8W3) 0 E UTC-8(-7DT) N47°48.56' W119°38.22' SEATTLE
 2272 B NOTAM FILE SEA
RWY 03-21: H2575X46 (ASPH) LIRL
RWY 03: Road.
RWY 21: Road.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 03: TORA-2400
RWY 21: TORA-2400
SERVICE: LGT Rwy 03-21 no rwy lgts northside of Rwy 21 end to midfield. Bcn tempo OTS.
AIRPORT REMARKS: Unattended. Possible turbulence from grain elevators north side of arpt. Rwy 03-21 has widespread, open unsealed cracks and joints. NW prkg has steep dropoff. Rwy 03-21 markings faded. Pilots bring own ropes. Lgtd wind tee.
AIRPORT MANAGER: 509-884-4700
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

MARTIN FLD (See COLLEGE PLACE on page 230)