

**MOLOKAI**

**KALAUAPAPA** (LUP)(PHLU) 2 N UTC-10 N21°12.66' W156°58.42'

24 B TPA—800(776) NOTAM FILE MKK

**RWY 05-23:** H2700X75 (ASPH) S-17 MIRL

**RWY 05:** PAPI(P2L)—GA 3.0° TCH 19'

**RWY 23:** Rgt tfc.

**SERVICE:** LGT ACTVT MIRL Rwy 05-23 med instst only—CTAF. PAPI Rwy 05 daytime VFR use only. Rwy 05 PAPI unusbl byd 2.2 NM. Terrain penetrates PAPI safety slope at 2.7 NM.

**AIRPORT REMARKS:** Attended Mon-Fri 1700-0130Z. PPR from State Department of Health, Communicable Disease Division to enter settlement area phone Honolulu (808) 586-4580. 24 hrs PPR for Division 1.1, 1.2, 1.3 explosives and 4 hrs PPR for other hazardous material in/out of arpt ctc (808) 567-9660/9663. Deer and wild animals on and invof arpt at night. Oct-May large waves impacting shoreline resulting in salt water sprays 40' high. NOTE: See Area Notices—TRAFFIC ADVISORIES AT NON-TOWER ARPTS.

**AIRPORT MANAGER:** (808) 872-3830

**COMMUNICATIONS:** CTAF 122.9

**MOLOKAI RCO** 122.1R 116.1T (HONOLULU RADIO)

® **HCF CENTER APP/DEP CON** 124.1

**CLEARANCE DELIVERY PHONE:** For CD ctc Honolulu Control Facility at 808-840-6262.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE MKK.

**MOLOKAI (H) VORTAC** 116.1 MKK Chan 108 N21°08.29' W157°10.05' 057° 11.7 NM to fld. 1421/11E.

VORTAC unusable:

275°-285° byd 25 NM blo 3,500'

HAWAIIAN ISLANDS

P-2G

IAP

