

MARLIN (T15) 3 NE UTC-6(-5DT) N31°20.44' W96°51.12'
411 B NOTAM FILE FTW
RWY 17-35: H3021X50 (ASPH) S-4 RWY LGTS(NSTD)

RWY 17: Trees.

RWY 35: Thld dsplcd 90'. Fence.

SERVICE: LGT Rwy 17-35 north 2900' lgtd. Rwy thr markings not coincident with thr lgts. Vegetation obscs lgts.

AIRPORT REMARKS: Unattended. Windssock may be unrel due to trees in proximity and mast not ver.

AIRPORT MANAGER: 254-275-0051

COMMUNICATIONS: CTAF 122.9

Ⓡ WACO APP/DEP CON 127.65 (1200-0600Z±)

Ⓡ FORT WORTH CENTER APP/DEP CON 133.3 (0600-1200Z±)

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE ACT.

WACO (VH) (H) VORTACW 115.3 ACT Chan 100 N31°39.73'
W97°16.14' 123° 28.8 NM to fld. 507/9E.

VOR unusable:

125°-149° byd 40 NM

149°-159° byd 47 NM

159°-187° byd 40 NM

188°-198° byd 40 NM blo 12,000'

199°-234° byd 40 NM

235°-245° byd 50 NM

246°-256° byd 40 NM blo 18,000'

246°-256° byd 52 NM

257°-267° byd 58 NM

268°-282° byd 40 NM

270°-335° byd 35 NM blo 4,000'

283°-293° byd 40 NM blo 6,000'

283°-293° byd 58 NM

294°-330° byd 40 NM

HOUSTON
L-19D, 21A
IAP

