

DAVIS MONTHAN THREE DEPARTURE (DMA3.DMA)

TUCSON, ARIZONA

DME required

Rwy	Knots	60	120	180	240	300	360
13 (a)	V/V(fpm)	240	480	720	960	1200	1440
31 (b)	V/V(fpm)	300	600	900	1200	1500	1800

Minimum Climb Rate


(a) to 3200

(b) HOTTT TRANS to 9200

ATIS ★ 270.1
 CLNC DEL
 121.8 275.8
 GND CON
 121.8 275.8
 TOWER
 118.85 253.5
 TUCSON APP/DEP CON
 119.4 269.55

EFFECTIVE BY NOTAM

During RADAR operations aircraft will receive RADAR vectors to appropriate transition.



(NARRATIVE ON FOLLOWING PAGE) 9413

DAVIS MONTHAN THREE DEPARTURE (DMA3.DMA)

Orig 05SEP24

TUCSON, ARIZONA
DAVIS-MONTHAN AFB (KDMA)

SW-4, 05 SEP 2024 to 03 OCT 2024

SW-4, 05 SEP 2024 to 03 OCT 2024