DUTCH LANDING STRIP (88AK) PVT 0 N UTC-9(-8DT) N60°32.42′ W150°52.08′ 300 NOTAM FILE Not insp.

RWY 07-25: 1300X100 (GRVL)

RWY 07: Trees.

RWY 25: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. AIRPORT MANAGER: 907-398-8999

COMMUNICATIONS: CTAF 122.5

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

ANCHORAGE

LAKEWOOD AIRSTRIP (53AK) PVT 5 NE UTC-9(-8DT) N60°32.03′ W150°51.39′

299 NOTAM FILE Not insp. RWY 02-20: 1200X60 (GRVL)

RWY 02: Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. Rwy 02-20 not plowed durg winter, silty sand base unusbl durg breakup. Rwy 02-20 sand/gravel.

AIRPORT MANAGER: 907-262-1552

COMMUNICATIONS: CTAF 122.5

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

ANCHORAGE

SCOOTERS LANDING STRIP (AK84) PVT 2 W UTC-9(-8DT) N60°31.77′ W150°49.85′

NOTAM FILE Not insp. RWY 08-26: 2400X80 (GRVL)

AIRPORT REMARKS: Unattended. PPR arpt rstd to owner or owner invited guests. No acft svcs avbl. Rwy conditions not monitored. Fly pat south of E-W rwy, twrs north. Pilots to conduct rwy visual inspection prior to use. Maintenance personnel and equipment have right of way. Wildlife invof rwy. Be alert, dsplcd thlds exist. Trees and p-lines penetrate apch sfcs. Arpt not fenced.

AIRPORT MANAGER: 907-398-9849

COMMUNICATIONS: CTAF 122 5

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737. Advisory frequency: 122.5. ------

STERLING AIR PARK (4ØAK) PVT 2 NW UTC-9(-8DT) N60°33.45′ W150°50.61′ ANCHORAGE

333 NOTAM FILE Not insp. RWY 08-26: 1809X60 (GRVL) AIRPORT REMARKS: Unattended. AIRPORT MANAGER: 907-262-5100 **COMMUNICATIONS: CTAF 122.5**

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

STEVENS VILLAGE (SVS)(PFSV) 1 NNE UTC-9(-8DT) N66°01.03′ W149°03.26′

FAIRBANKS H-1B, L-4J

ANCHORAGE

328 B NOTAM FILE FAI

RWY 05-23: 4000X75 (GRVL-DIRT)

RWY 05: REIL. PAPI(P4L)-GA 3.0° TCH 25'. Trees. RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.

SERVICE: LGT ACTVT REIL Rwy 05 and 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23-CTAF. ACTVT Rotg beacon-CTAF.

AIRPORT REMARKS: Unattended. Rwy 05-23 cond not monitored, rcmd visual inspection prior to Indg. Clsd rwy located 1 NM west of Rwy 05-23. Snow removal ops during winter, monitor CTAF. Rwy 05-23 marked with lgts and cones.

AIRPORT MANAGER: (907) 451-5280 **COMMUNICATIONS: CTAF 122.9**

RADIO AIDS TO NAVIGATION: NOTAM FILE FAI.

FAIRBANKS (H) (H) VORTACW 108.6 FAI Chan 23 N64°48.00′ W148°00.72′ 320° 77.8 NM to fld. 1526/21E.

TACAN AZIMUTH unusable:

065°-100° byd 30 NM

270°-330° byd 10 NM blo 10,000′

270°-330° byd 30 NM

COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.

