

ROUND LAKE (W57) 2 E UTC-5(-4DT) N42°55.87' W73°46.25'
178 NOTAM FILE BTV
RWY 14-32: 1927X76 (TURF) 1.0% up SE

NEW YORK

RWY 14: Tree.
RWY 32: Trees.

AIRPORT REMARKS: Attended on call. Deer on and in/ovf aprt. Arpt clsd to itinerant acct Nov-May. Rwy 14-32 has 80' trees rgt and left of centerline in primary sfc. Rwy 14-32 soft during spring (Mar-Jun). Military helicopters and ultralight acct use rwy. Access to arpt from lake overgrown. Ctc arpt mgr prior to seaplane arrival.

AIRPORT MANAGER: 518-899-6316
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Albany Apch at 518-862-2299.

• • • • •
WATERWAY 14W-32W: 4000X600 (WATER)

ROYALTON (See GASPORT on page 202)

SANDS POINT SPB (See PORT WASHINGTON on page 233)

SARANAC LAKE

ADIRONDACK RGNL (SLK)(KSLK) 4 NW UTC-5(-4DT) N44°23.12' W74°12.37'

MONTREAL
H-11C, 12K, L-32G
IAP, AD

1663 B LRA ARFF Index—See Remarks NOTAM FILE SLK
RWY 05-23: H6573X150 (ASPH-GRVD) S-40, D-73, 2S-92, 2D-115

PCN 64 F/B/W/T HIRL 0.3% up NE
RWY 05: PAPI(P4L)—GA 3.0° TCH 35'. Trees.
RWY 23: MALSR. Trees.

RWY 09-27: H3997X100 (ASPH) S-40, D-73, 2S-92, 2D-115
PCN 61 F/B/W/T MIRL
RWY 09: Trees.
RWY 27: Thld dspld 400'. Trees.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 05: TORA-6573 TODA-6573 ASDA-6573 LDA-6573
RWY 09: TORA-3997 TODA-3997 ASDA-3997 LDA-3997
RWY 23: TORA-6573 TODA-6573 ASDA-6333 LDA-6333
RWY 27: TORA-3997 TODA-3997 ASDA-3997 LDA-3597

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE HIRL Rwy 05-23, MIRL Rwy 09-27, MALSR Rwy 23, PAPI Rwy 05 and twy lgts—CTAF.

AIRPORT REMARKS: Attended May-Oct 1100-0200Z±. Nov-Apr 1100-0100Z±. For arpt attendant after hrs call 518-637-7329. Rwy/twy/apron conds not mnt outside of nml atnd hrs. All sfc work in prog; grass cutting Apr thru Oct. Class IV, ARFF Index A. PPR 48 hr for unscheduled acct ops with more than 30 passenger seats call arpt manager 518-891-4600 ext 106. Index B coverage is avbl. Twy B unavbl to acct with wingspan 79' and abv. Abv ground twy edge lgts adjacent to Twy B tie down apron area. Rwy 09 NSTD markings, thld markings 400' from rwy end. Cold temperature airport. Altitude correction required at or below -29C. Ldg fee.

AIRPORT MANAGER: 518-891-4600

WEATHER DATA SOURCES: ASOS 124.175 (518) 891-6696.

COMMUNICATIONS: CTAF/UNICOM 123.0

BOSTON CENTER APP/DEP CON 120.35


CLEARANCE DELIVERY PHONE: For CD if una to ctc on freq, ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE SLK.

SARANAC LAKE (L) DME 109.2 SLK Chan 29 N44°23.07' W74°12.27' at fld. 1647.

DME unusable:
089°-104° byd 25 NM blo 10,000'
105°-110° byd 25 NM
111°-165° byd 25 NM blo 10,000'
300°-350° byd 36 NM blo 10,000'

ILS 108.9 I-SLK Rwy 23. Class IA. Unmonitored.



SARATOGA CO (See SARATOGA SPRINGS on page 238)