

DANVILLE RGNL (DAN)(KDAN) 3 E UTC-5(-4DT) N36°34.35' W79°20.18'

571 B TPA—See Remarks NOTAM FILE DAN

CINCINNATI

H-9C, 121, L-261, 36G

IAP

RWY 02-20: H5900X100 (ASPH-GRVD) S-90, D-130, 2S-165

HIRL 0.5% up N

RWY 02: MALSR. PAPI(P4L)—GA 3.0° TCH 55'. Tree.**RWY 20:** REIL. PAPI(P4L)—GA 3.0° TCH 47'. Thld dspcd 300'. Tree.**RWY 13-31:** H3910X100 (ASPH) S-90, D-130, 2S-165 MIRL

1.1% up NW

RWY 13: REIL. VASI(V2L)—GA 3.0° TCH 28'. Tree.**RWY 31:** REIL. PAPI(P2L)—GA 4.0° TCH 76'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 02:** TORA-5600 TODA-5900 ASDA-5600 LDA-5600**RWY 20:** TORA-5900 TODA-5900 ASDA-5900 LDA-5600**SERVICE:** S4 FUEL 100LL, JET A+ LGT ACTIVATE HIRL Rwy 02-20,

MIRL Rwy 13-31, REIL Rwy 13, Rwy 31, and Rwy 20, MALSR Rwy

02, VASI Rwy 13 and PAPI Rwy 02, Rwy 20 and Rwy 31—CTAF.

AIRPORT REMARKS: Attended 1200-0000Z. Arpt unattended Christmas

Day. Birds and deer on and invof arpt. Trees penetrating 7:1

transitional sfc of Rwy 31 both sides, first 1000'. Ctc arpt

administration prior to conducting specialized aero activities

434-799-5110. TPA-1371 (800) lgt acft, 2071 (1500) turbine

acft. Rwy 02 is designated calm wind rwy.


AIRPORT MANAGER: 434-799-5110**WEATHER DATA SOURCES:** ASOS 128.125 (434) 799-1701.**COMMUNICATIONS:** CTAF/UNICOM 123.05

RCO 122.2 (LEESBURG RADIO)

® WASHINGTON CENTER APP/DEP CON 124.05

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Washington ARTCC at 703-771-3587.**AIRSPACE:** CLASS E svc continuous.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DCA.**SOUTH BOSTON (L) (L) VORTAC** 110.4 SBV Chan 41 N36°40.50' W79°00.87' 254° 16.7 NM to fld. 520/5W.

ILS 110.7 I-DAN Rwy 02. Class IE.

**DAVEE** N38°39.70' W77°06.61' NOTAM FILE DCA.**NDB (HW) 223 DAA** 323° 4.6 NM to Davison AAF. 53/9W.

Unusable:

Byd 15 NM

WASHINGTON

L-29E, 34E, 36I