

NUGENT CHAMBERLAIN LAKE SPB (39B) 11 NE UTC-5(-4DT) N46°12.15' W69°14.42'
 945 NOTAM FILE BGR
WATERWAY 13W-31W: 15000X1100 (WATER)
SEAPLANE REMARKS: Attended continuously. For svcs call 207-944-5991 in advance.
AIRPORT MANAGER: 207-944-5991
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

MONTREAL


CURRIER'S SPB (See GREENVILLE JUNCTION on page 71)

CUTLER RGNL (ME2) 2 W UTC-5(-4DT) N44°40.80' W67°15.86'
 55 NOTAM FILE BGR
RWY 09-27: 2950X40 (GRVL)
RWY 09: P-line.
RWY 27: Tree. Rgt tfc.
AIRPORT REMARKS: Unattended. Arpt clsd Nov through Apr. Wildlife on and invof arpt. Land Rwy 27 when wind is lgt and variable. Rwy 09-27 grvl stabilized with grass. Rwy 09-27 center 20' of rwy well mowed.
AIRPORT MANAGER: 207-266-3797
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

HALIFAX

DEBLOIS FLIGHT STRIP (43B) 2 SE UTC-5(-4DT) N44°43.61' W67°59.48'
 218 NOTAM FILE BGR
RWY 15-33: H4500X75 (ASPH) S-84, D-200, 2D-400
AIRPORT REMARKS: Unattended. Clsd winter months except to ski acft.
 Pavement drop-offs at thlds of Rwy 15 and Rwy 33 in excess of 5".
 Rwy could have loose grvl trkd onto sfc by vehicular tfc. Men and equip could be near or on rwy sfc durg summer months. Dalgt use only. Rwy 15 nrs and cntrln faded or misg. Rwy 33 nrs and cntrln faded or misg.
AIRPORT MANAGER: 207-941-4502
COMMUNICATIONS: CTAF 122.9
 Ⓡ BOSTON CENTER APP/DEP CON 124.25
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.
RADIO AIDS TO NAVIGATION: NOTAM FILE BGR.
BANGOR (VH) (H) VORTACW 114.8 BGR Chan 95 N44°50.51'
 W68°52.44' 119° 38.3 NM to fld. 360/19W.

HALIFAX
 L-321
 IAP



DEWITT FLD/OLD TOWN MUNI (See OLD TOWN on page 79)