

**CLE ELUM**

**CLE ELUM MUNI** (S93) 1 E UTC-8(-7DT) N47°11.65' W120°53.04' **SEATTLE**  
 1945 B NOTAM FILE SEA  
**RWY 07-25:** H2379X60 (ASPH) MIRL 0.3% up W  
**RWY 07:** REIL. PAPI(P2L)—GA 4.0° TCH 20'. Rgt tfc.  
**RWY 25:** REIL. PAPI(P2L)—GA 4.0° TCH 20'.  
**SERVICE:** LGT Actvt REIL Rwy 07 and 25; MIRL Rwy 07-25—CTAF. PAPI Rwy 07 and 25 oper cons. Actvt rotg bcn—CTAF.  
**AIRPORT REMARKS:** Unattended. Wildlife on and invof rwy. Ditch 75' ft fm cntrn runs len of northside of rwy. Rwy 07-25 markings are faded.  
**AIRPORT MANAGER:** 509-674-2262  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.  
**COMM/NAV/WEATHER REMARKS:** Gliders use CTAF freq 122.3.

**DE VERE FLD** (2W1) 3 E UTC-8(-7DT) N47°10.65' W120°51.16' **SEATTLE**  
 1800 NOTAM FILE SEA  
**RWY 08-26:** H2055X30 (ASPH)  
**RWY 08:** Trees. Rgt tfc.  
**RWY 26:** Trees.  
**AIRPORT REMARKS:** Attended dalgt hrs. Fld occasionally CLOSED in winter. Wildlife on and invof rwy. Rwy 08-26 has 2 inch dropoff along entr rwy both sides. Rwy 08-26 svr unsealed cracks and joints. Rwy 08-26 NSTD mrkgs no nrs, small and square aiming points painted on rwy ends. All patterns to the south. Rwy 08-26 mrkgs faded.  
**AIRPORT MANAGER:** 509-962-2066  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

**COLFAX**

**LOWER GRANITE STATE** (ØØW) 12 S UTC-8(-7DT) N46°40.37' W117°26.50' **SEATTLE**  
 719 NOTAM FILE SEA  
**RWY 14-32:** 3400X50 (GRVL) 0.9% up SE  
**RWY 14:** Trees.  
**RWY 32:** Hill.  
**AIRPORT REMARKS:** Unattended. Do not land if snow present on rwy. No winter snow removal ops. Pedestrians, vehicles and animals on and invof rwy. Ctc WA State Aviation Division 360-709-8015 or 1-800-552-0666 WA area for facility info prior to use. For acct accidents/incidents ctc WA state emergency operations center 800-258-5990. Ck density altitude. Gravel portions of rwy sfc rough and soft. Rwy marked with reflectors dur dates arpt is open. Steep drop off on both sides of runway.  
**AIRPORT MANAGER:** (360) 618-2477  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

**PORT OF WHITMAN BUSINESS AIR CENTER** (S94) 3 SW UTC-8(-7DT) N46°51.52' W117°24.84' **SEATTLE**  
 2181 B TPA—3010(829) NOTAM FILE SEA **L-13B**  
**RWY 08-26:** H3209X60 (ASPH) S-17 MIRL 1.0% up E  
**RWY 08:** Thld dsplcd 492'. Road.  
**RWY 26:** Thld dsplcd 450'. Hill.  
**RUNWAY DECLARED DISTANCE INFORMATION**  
**RWY 08:** TORA-3209 TODA-3209 ASDA-3209 LDA-2718  
**RWY 26:** TORA-3209 TODA-3209 ASDA-3209 LDA-2890  
**SERVICE:** LGT ACTIVATE MIRL Rwy 08-26—CTAF.  
**AIRPORT REMARKS:** Attended Jan-Dec 1600-0000Z±. Deer invof rwy. Watch for birds invof creek south of arpt. Rwy 08-26 farm machinery may be opr in flds on both sides of rwy and off both rwy ends. 30' bldg 250' south AER 26. Dense agricultural ops Feb-Oct.  
**AIRPORT MANAGER:** 509-397-2061  
**COMMUNICATIONS:** CTAF/UNICOM 122.8  
**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

CONTINUED ON NEXT PAGE

## CONTINUED FROM PRECEDING PAGE

RADIO AIDS TO NAVIGATION: NOTAM FILE PUW.

PULLMAN (VL) (L) VOR/DME 117.15 PUW Chan 118(Y) N46°40.45' W117°13.41' 305° 13.6 NM to fld.

2772/20E. DME unmonitored.

DME unusable:

040°-045° byd 35 NM blo 8,000'

065°-070° byd 30 NM blo 7,000'

090°-095° byd 35 NM blo 7,000'

VOR unusable:

032°-100° byd 40 NM

155°-195° byd 40 NM

## COLLEGE PLACE

MARTIN FLD (S95) 1 W UTC-8(-7DT) N46°02.82' W118°25.03'

SEATTLE

750 NOTAM FILE SEA

L-13A

RWY 05-23: H3819X60 (ASPH) S-12 LIRL(NSTD)

RWY 05: VASI(V2L).

RWY 23: VASI(V2R). Road.

SERVICE: S2 FUEL 100LL LGT Rwy 05-23 NSTD LIRL southwest 1240' medium ints. Arpt lgtg opr from dusk until 1000Z±. ACTIVATE NSTD LIRL Rwy 05-23 and VASI Rwy 05 and Rwy 23—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z±. Call in advn 509-386-0000. 24 hr self svc credit card fueling facility. Gliders and other acft perform ops on turf btn Rwy 05-23 and twy. Overnight parking fee of \$3.00. Pvt road crosses 700' from southwest end of rwy. 2/3 of the rwy has wdspr, opn, unsealed cracks and joints, hi lvl of raveling and alligator cracking. Ldg fee.

AIRPORT MANAGER: 509-386-0000

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Spokane Apch at 509-742-2525, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE ALW.

WALLA WALLA (VL) (DH) VOR/DME 116.4 ALW Chan 111 N46°05.22' W118°17.55' 231° 5.7 NM to fld.  
1150/14E.

VOR unusable:

016°-071° byd 31 NM blo 12,500'

032°-042° byd 40 NM blo 12,500'

032°-042° byd 62 NM

042°-169° byd 40 NM

071°-101° byd 20 NM blo 14,500'

101°-146° byd 20 NM blo 13,500'

256°-285° byd 40 NM

286°-296° byd 40 NM blo 4,000'

286°-296° byd 50 NM

291°-302° byd 40 NM

309°-319° byd 40 NM blo 4,000'

309°-319° byd 85 NM

320°-031° byd 40 NM

DME unusable:

071°-101° byd 20 NM blo 14,500'

116°-071° byd 31 NM blo 12,500'

146°-151° byd 20 NM blo 11,500'

COLVILLE MUNI (63S) 1 E UTC-8(-7DT) N48°32.65' W117°53.01'

SEATTLE

1888 B NOTAM FILE SEA

RWY 01-19: H2695X40 (ASPH) S-11 MIRL

RWY 19: Tree.

SERVICE: FUEL 100LL LGT Dusk-dawn. ACTIVATE MIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1600-0100Z±. Watch for deer on and invof arpt. Rwy 19 dthr 255'. When ldg Rwy 19, bright lghts around high school stadium, aprx 3/4 miles south of arpt. Ocnl vehicular tfc across end of Rwy 01-19 and twy. Grass ldg area avbl across Rwy 01-19 1500'X150'. Hazards are 50' obst on both ends, trees/poles. Apron and tiedown grvl; 3 asph paved transient tiedowns westside. Eastside tiedowns gravel. 2 car avbl.

AIRPORT MANAGER: 509-685-9056

WEATHER DATA SOURCES: AWOS-3 119.275 (509) 684-8994.

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.