

COLUMBIA (022) 1 SW UTC-8(-7DT) N38°01.83' W120°24.87'

SAN FRANCISCO

2121 B TPA—See Remarks NOTAM FILE RIU

L-3B

RWY 17-35: H4673X75 (ASPH) S-30 MIRL 1.0% up N

IAP

RWY 17: REIL. VASI(V2L)—GA 4.55° TCH 56'. Thld dspcd 598'.
Ground. Rgt tfc.

RWY 35: REIL. VASI(V2L)—GA 4.0° TCH 54'. Thld dspcd 384'.
Trees.

RWY 11-29: 2607X50 (TURF) 0.9% up W

RWY 11: Trees. Rgt tfc.

RWY 29: Trees.

SERVICE: S4 FUEL 100LL, JET A OX 2, 4 LGT Rwy 35 VASI unusable
byd 5° left and 5° right of rwy centerline. ACTIVATE MIRL Rwy 17-35
and REIL Rwy 17 and Rwy 35—CTAF. VASI Rwy 17 and Rwy 35 opr
continuously.

AIRPORT REMARKS: Attended 1600-0100Z±. CAUTION: Rwy 11 departures
prohibited due to conflict with main rwy. Varying wind direction and
velocity may be encountered at mid point of Rwy 17-35 due to terrain
features and wind flow patterns. Rwy 29 not recommended for use
during winter months Nov through Mar. Turf twy north side of Rwy
11-29 not recommended for use Nov-Mar. All jet act are requested to
land Rwy 35 and depart Rwy 17 wind and weather permitting. Arpt has
two rotating beacons, one on the arpt and one 6500' SE threshold Rwy
35. Calfire Air Tanker ops from arpt during fire season. Ldg fee for all
commercial operators regardless of size and corporate act over 12,500 pounds gross ldg weight. Avoid flights over
Columbia State Park NE of arpt, and Highway 49 bridge 5 NM southwest of arpt and vicinity. Helicopter parking area
300' by 120' (4 positions). TPA Rwy 11-29 2921(800).



AIRPORT MANAGER: (209) 533-6684

WEATHER DATA SOURCES: AWOS-3 124.65 (209) 536-9384.

COMMUNICATIONS: CTAF/UNICOM 122.975

Ⓡ NORCAL APP/DEP CON 125.1 (West-North)

Ⓡ OAKLAND CENTER APP/DEP CON 121.25 (East-South)

CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-0516.

RADIO AIDS TO NAVIGATION: NOTAM FILE RIU.

LINDEN (VH) (DH) VORW/DME 114.8 LIN Chan 95 N38°04.47' W121°00.23' 078° 28.1 NM to fld. 266/17E.

DME unusable:

191°-235°

VOR unusable:

228°-232° byd 40 NM

236°-240° byd 40 NM

COLUSA CO (008) 3 S UTC-8(-7DT) N39°10.74' W121°59.60'

SAN FRANCISCO

49 B TPA—849(800) NOTAM FILE RIU

L-2G, 3A

RWY 14-32: H3034X59 (ASPH) S-10 MIRL

IAP

RWY 14: PAPI(P2L)—GA 3.0° TCH 25'.

RWY 32: PAPI(P2L)—GA 3.0° TCH 43'. Road. Rgt tfc.

SERVICE: S4 FUEL 100LL LGT ACTVT MIRL Rwy 14-32 CTAF.

AIRPORT REMARKS: Attended dawn-dusk. Fuel avbl by credit card 24 hrs.

Be alert to bldg 120' above ground level, 1000' West. Birds on and
invof of arpt.

AIRPORT MANAGER: 530-682-2612

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓡ OAKLAND CENTER APP/DEP CON 132.2

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

RADIO AIDS TO NAVIGATION: NOTAM FILE RIU.

WILLIAMS (L) (L) VORTACW 114.4 ILA Chan 91 N39°04.27'

W122°01.64' 356° 6.7 NM to fld. 49/18E.

