260

ALASKA

HUNT STRIP (1ØAK) PVT 10 V 200 NOTAM FILE Not insp. RWY 07-25: 800X80 (GRVL) RWY 25: P-line.	V UTC-9(-8DT)	N61º35.51′V	V149°40.67´	ANCHOR/
AIRPORT REMARKS: Unattended. Ap Airport Manager: 907-373-3062 Communications: CTAF 122.8 Comm/NAV/WEATHER REMARKS: For a				ıs okay.
370 NOTAM FILE ENA WATERWAY 18W-36W: 4000X200 (V SEAPLANE REMARKS: Unattended. R northwest of lake.	wy frozen in winter.			ANCHOR
AIRPORT MANAGER: 907-376-8069 Communications: CTAF 122.8 Comm/Nav/Weather Remarks: For a		ai FSS dial 1–866	6-864-1737.	
300 NOTAM FILE ENA WATERWAY 09W-27W: 5000X2500				ANCHOR
SEAPLANE REMARKS: Unattended. B pub dock NE shore. Short term AIRPORT MANAGER: 907-269-8400 COMMUNICATIONS: CTAF 122.8 COMMUNICATIONS: TAF 122.8	n mooring—907–37	3–1776.		bris. Apch ovr city. Sm
LAWRENCE AIRSTRIP (55AK) PV 200 NOTAM FILE Not insp. RWY 04-22: 1700X25 (TURF) RWY 04: Trees. RWY 22: Trees. AIRPORT REMARKS: Unattended. Rw AIRPORT MANAGER: 907-354-6770 COMMUNICATIONS: CTAF 122.8 COMMUNICATIONS: FOR a	<i>r</i> y soft during spring	breakup.		ANCHOR
LINCOLN VILLAGE AIRPARK (89, 250 NOTAM FILE Not insp. RWY 16-34: 2000X200 (GRVL) AIRPORT REMARKS: Unattended. Rw AIRPORT MANAGER: (907) 841-493 COMMUNICATIONS: CTAF 122.8 COMM/NAV/WEATHER REMARKS: For a	vy 16–34 slopes up 3	to the middle of t ai FSS dial 1–866	he fld from both ends. Rw 5–864–1737.	
NIKLASON LAKE SPB (4AKØ) 380 NOTAM FILE ENA WATERWAY E-W: 2700X75 (WATEF SEAPLANE REMARKS: Unattended. N dock. All other property is pvt/n Caution, northwest end of lake AIRPORT MANAGER: 907-230-7943 COMMUNICATIONS: CTAF 122.8 COMM/NAV/WEATHER REMARKS: For a	o service of any type on-commercial. Eas has recreational ac	F) N61°37.75 e avbl to tran acft it shore of lake has tivity all year rour	. Public beaching access o s tall trees/hill. Boating acti Id.	
PIPER LANDING (AK25) PVT 350 NOTAM FILE Not insp. RWY 06-24: 1200X50 (TURF) RWY 06: Rgt tfc.	5 NW UTC-9(-8	–––––––– DT) N61°37.0	5′W149º36.88′	ANCHOR