NORTH DAKOTA

FESSENDEN-STREIBEL MUNI 1619 NOTAM FILE GFK RWY 08-26: 2940X120 (TURF) RWY 08: Road. RWY 26: Trees.	LIRL		N47°39.58′ W99°39.66	Y TWIN CITIES
SERVICE: LET ACTIVATE LIRL AIRPORT REMARKS: Unattended. V and stopway areas. Rwy 08 condition prior to use Oct-AJ AIRPORT MANAGER: 701-653-506 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: FOR C	Vaterfowl and dee has lgtd 300´ sto or. 59	er on or invof arpt opway and Rwy 26	i has 550′ lgtd stopway. No	gt cone markers at rwy thids, snow removal avbl—confirm
FORT YATES				
1634 B NOTAM FILE GF RWY 14-32: H3699X60 (ASPH) RWY 14: PAPI(P2L)—GA 3.0° RWY 32: PAPI(P2L)—GA 3.0° RUNWAY DECLARED DISTANCE INFOR RWY 14: TORA-3699 TODA RWY 32: TORA-3699 TODA	S-11.5 MIRL 2 TCH 30'. 2 TCH 30'. Fence MATION -3699 ASDA-3 -3699 ASDA-3	3699 LDA-369 3699 LDA-369	9	TWIN CITIES L-14F
ACTVT—CTAF. AIRPORT REMARKS: Unattended. I 701-455-1811; 701-854- AIRPORT MANAGER: 701-301-746 Communications: CTAF 122.9	Birds & waterfowl -8622. Gate code 53	on & invof arpt. (e protected – local	Cfm snow removal Oct–Apr; (zip code.	
CLEARANCE DELIVERY PHONE: FOR C Radio Aids to Navigation: Nota Bismarck (VL) (DH) Vorw/DME 1854/12E.	M FILE BIS.		463-5588. 46°45.71′W100°39.92′	166° 41.7 NM to fld.
	and of rwy due to and possible anir ear rwy midpt. 1	er due to lack of s rwy gradient. +5 nal holes. Be alerf	now removal. Birds on and ir ´hill 60´R of AER. Rwy 17 t, Rwy 08 first 200´rise at 5	–35 and Rwy 08–26 turf
GARRISON DAM RECREATIONAL	AIRPARK (See	RIVERDALE on p	age 358)	
GARRISON MUNI (DØ5) 1 V 1937 B NOTAM FILE GF RWY 13-31: H3699X60 (ASPH) RWY 13: PAPI(P2L)—GA 3.0° RWY 03-21: 2618X120 (TURF) RWY 03: Road.	K S–12.5 MIRL 7 TCH 29'. Road.	0.8% up NW	W101°26.21′	BILLINGS L—14F IAP
RWY 21: Trees. SERVICE: FUEL 100LL LGT A AIRPORT REMARKS: Unattended. 2 ctc arpt manager or City Hal	4 hr self svc cred	it card fuel avbl. V		f arpt. Confirm snow removal