MC CLUSKY MUNI (7G2) 2 SW UTC-6(-5DT) N47°27.72′ W100°29.23′

TWIN CITIES

1900 NOTAM FILE GFK

RWY 13-31: 3136X80 (TURF) 0.3% up NW

AIRPORT REMARKS: Unattended. Cfm ireg snow removal & winter conds with amgr prior to use. Snow removal emerg only call 701–220–4365. Rwy 13–31 has nmrs grass clumps.

AIRPORT MANAGER: 701-220-4365 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

MC VILLE MUNI (8M6) 1 NW UTC-6(-5DT) N47°46.22′ W98°11.09′

TWIN CITIES

1473 NOTAM FILE GFK

RWY 18-36: 2500X90 (TURF)

RWY 18: Road.

RWY 13-31: 2277X100 (TURF) LIRL

RWY 13: Road. RWY 31: Bldg.

SERVICE: LGT ACTIVATE LIRL Rwy 13-31 -CTAF.

AIRPORT REMARKS: Unattended. Call arpt manager to confirm snow removal 701–270–2820. Rwy 13–31 200′ turf stopway on northwest end and 500′ turf stopway on southeast end. Rwy 13–31 turf surface rolling, Rwy 36 has multiple 110′ bldgs 1400′ fm thld; L and R of cntrln. Rwy 36 has 40′ trees 175′ fm thld; L 110′ L of cntrln. Rwy 31 has 40′ trees 720′ fm thld; L and R of cntrln.

AIRPORT MANAGER: (701) 739-1345

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

MERCER CO RGNL (See HAZEN on page 342)

MILNOR MUNI (4R6) 1 E UTC-6(-5DT) N46°15.50′ W97°26.27′

TWIN CITIES

1091 NOTAM FILE GFK RWY 08-26: 2210X90 (TURF)

RWY 08: Road.

AIRPORT REMARKS: Unattended. Deer and birds on or invof arpt. Confirm arpt condition prior to Idg due to irregular snow removal, phone request only 701–680–1001. Rwy 08–26 crosswind turbulence due to close proximity tree growth, additionally, tress to north and south, windsocks and buildings to the north of rwy penetrate 7:1 transitional surface. Rwy 08–26 has 250′ turf stopway west end.

AIRPORT MANAGER: 701-680-1001 Communications: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.