


**LUCKY LANDING MARINA SPB** (See BANGOR on page 59)

**MACHIAS VALLEY** (MVM)(KMVM) 1 SW UTC-5(-4DT) N44°42.19' W67°28.72'  
 96 B NOTAM FILE BGR  
**RWY 18-36:** H2880X60 (ASPH) S-12.5 MIRL 0.9% up N  
**RWY 36:** REIL. Pole.  
**SERVICE:** FUEL 100LL LGT ACTVT REIL Rwy 36; MIRL Rwy 18-36—CTAF.  
**AIRPORT REMARKS:** Unattended. Deer and wildlife on and invof arpt. 100LL fuel 24 hr self svc with major credit card.  
**AIRPORT MANAGER:** 207-271-0808  
**WEATHER DATA SOURCES:** AWOS-AV 122.8 (207) 255-2511.  
**COMMUNICATIONS:** CTAF/UNICOM 122.8  
 Ⓡ BOSTON CENTER APP/DEP CON 124.25  
 CLNC DEL 122.5 (BANGOR RADIO)  
**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.  
**RADIO AIDS TO NAVIGATION:** NOTAM FILE BGR.  
**BANGOR (VH) (H) VORTACW** 114.8 BGR Chan 95 N44°50.51' W68°52.44' 116° 60.2 NM to fld. 360/19W.

HALIFAX  
L-321  
IAP



**MEDDYBEMPS**

**GILLESPIE FLD** (66B) 1 W UTC-5(-4DT) N45°01.78' W67°21.96'  
 200 NOTAM FILE BGR  
**RWY 16-34:** 1635X50 (TURF)  
**RWY 16:** Trees.  
**RWY 34:** Trees.  
**AIRPORT REMARKS:** Unattended. Rwy 16-34 temporarily CLOSED and not being maintd. Rwy not plowed winter months. 36' pwr ln 280' N of Rwy 16 mkd with balls.  
**AIRPORT MANAGER:** 603-726-6587  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.

HALIFAX

**MERRYMEETING FLD** (See BOWDOINHAM on page 61)

**MILLINOCKET**

**MILLINOCKET SPB** (7ØB) 7 NW UTC-5(-4DT) N45°43.70' W68°50.67'  
 492 NOTAM FILE BGR  
**WATERWAY ALL-WAY:** 4000X500 (WATER)  
**SERVICE:** FUEL 100LL  
**SEAPLANE REMARKS:** Attended May-Oct dawn-dusk. Arpt clsd 31 Oct through 30 Apr. Water level fluctuates 10' +/- lowest in Sep and Oct. Preferred tkf and ldg direction for SPB Rwy 04-22. Significant amount of boat activity sharing sea lanes. Buoys have been added to identify rocks at low water levels. Location of buoys rqr tkf and ldg direction of Rwy 04-22 with buoys at outer edges of sea lane. Unlighted 199' cell twr located 2 SM at 132° from dock. Twr underlies downwind to baseleg of pattern when ldg to the southwest.  
**AIRPORT MANAGER:** 207-723-8378  
**COMMUNICATIONS:** CTAF 122.9  
**CLEARANCE DELIVERY PHONE:** For CD ctc Boston ARTCC at 603-879-6859.

HALIFAX