OREGON

2680 NOTAM FILE MMV RWY 13-31: 1840X30 (DIRT)	SW UTC-8(-7	DT) N43°25.49′W	117°20.74´	KLAMATH FALL
RWY 13: Trees. AIRPORT REMARKS: Unattended. Owner advises ctc with State Department of Aviation 503–378–4880 prior to use. Remoi arpt, no ground access. Arpt in canyon, surrounded by high terrain. 4 ' brush growth within 20 ' of rwy edge. Rwy 13– irregular maintenance. Rwy surface frequently rough and rutted. Sur conds not rprtd. AIRPORT MANAGER: 503-378-4880 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.				
PACIFIC CITY STATE (PFC)(KPFC) 1 S 10 NOTAM FILE MMV RWY 14-32: H1860X30 (ASPH) S-7 RWY 14: Tree. AIRPORT REMARKS: Unattended. Owner advis under water dur winter high tides. Ocnl recommended and may not be possible	driftwood on rwy . Many close in ot	rtment of Aviation 503– due to flooding. Sfc con st on both sides of rwy.	378–4880 prior to us Ids not rprtd. Downwi Exp low level turbuler	nd ldgs not nce dur crosswind
cond. Assorted trees and 40' p-line at only. AIRPORT MANAGER: 503-378-4880 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Seatt			os to be conducted at	the parking ram
PAISLEY (22S) 3 NW UTC-8(-7DT) 4395 B NOTAM FILE MMV RWY13-31: H4300X60 (ASPH) LIRL AIRPORT REMARKS: Unattended. Rwy 13 has AIRPORT MANAGER: 541-947-4222 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Seatt RADIO AIDS TO NAVIGATION. NOTAM FILE LKY	0.4% up SE a aiming points. ele ARTCC at 253			KLAMATH FAL L-1;
LAKEVIEW (VH) (H) VORTACW 112.0 LKV VOR unusable: 120°-142° byd 40 NM 143°-153° byd 117 NM 143°-153° byd 40 NM bio 11,000′ 143°-153° byd 40 NM bio 14,000′ 154°-160° byd 40 NM 161°-171° byd 40 NM		2°29.57′ W120°30.43	′ 331º 13.7 NM t	o fld. 7465/19E