

DRYDEN

TERRELL CO (6R6) 5 W UTC-6(-5DT) N30°02.79' W102°12.79'

SAN ANTONIO

2323 B NOTAM FILE SJT

L-19A

RWY 13-31: H4526X75 (ASPH) S-30 MIRL 0.7% up NW

RWY 13: Fence.

RWY 04-22: H4525X75 (ASPH) S-30 0.3% up SW

RWY 22: Brush.

SERVICE: LGT Actvt MIRL Rwy 13-31—CTAF. Heli pad lgts, 5 clicks—123.05.

AIRPORT REMARKS: Attended intmnt. Rwy 04-22 and Rwy 13-31 extensive cracking, loose stones on sfc. Rwy 13-31 and Rwy 04-22 marking poor due to pavement deterioration.

AIRPORT MANAGER: 432-345-6731

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE FST.

FORT STOCKTON (VH) (H) VORTACW 116.9 FST Chan 116 N30°57.13' W102°58.54' 133° 67.1 NM to fld. 2893/11E.

VOR unusable:

020°-055° byd 20 NM blo 6,900'

070°-086° byd 35 NM blo 6,400'

106°-132° byd 30 NM blo 5,900'

125°-202° byd 40 NM

203°-213° byd 40 NM blo 18,000'

214°-230° byd 40 NM

245°-255° byd 40 NM

315°-330° byd 30 NM blo 5,400'

DUBLIN MUNI (9F0) 2 SE UTC-6(-5DT) N32°04.09' W98°19.52'

DALLAS-FORT WORTH

1495 B NOTAM FILE FTW

L-17B

RWY 15-33: H3200X60 (ASPH) S-12.5 MIRL

RWY 15: P-line.

SERVICE: FUEL , UL94 LGT ACTIVATE MIRL Rwy 15-33 —123.5.

AIRPORT REMARKS: Attended Wed-Fri 1500-0300Z†, Sat 1500-2000Z†.

Deer and wildlife on and in/ovf arpt.

AIRPORT MANAGER: (254) 434-1082

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

GLEN ROSE (L) TACAN Chan 97 JEN (115.0) N32°09.58' W97°52.66' 251° 23.5 NM to fld. 1300/6E.

