

PONDER**HICKS** (74T) 2 E UTC-6(-5DT) N33°10.98' W97°15.28'**DALLAS—FT WORTH**

725 NOTAM FILE FTW

H-6H, L-17C**RWY 17-35:** 2364X90 (TURF)**RWY 17:** Bldg. Rgt tfc.**RWY 35:** Fence.**AIRPORT REMARKS:** Unattended. Tfc in the pat shall remain at or below 1,300 ft MSL. Rwy defined by mowing. 30 ft trees, 40 ft R and L of rwy cntrln. 6 ft washout along W side of rwy. Rwy rough and uneven. Arpt fenced. Gates locked. No public ingress or egress.**AIRPORT MANAGER:** 940-479-2114**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Regional Apch at 972-615-2799.**PORT ARANSAS****MUSTANG BEACH** (RAS)(KRAS) 2 SW UTC-6(-5DT) N27°48.71' W97°05.33'**BROWNSVILLE**

5 B NOTAM FILE RAS

L-201, 21A, GOMW**RWY 12-30:** H3482X70 (ASPH) MIRL**IAP****RWY 12:** PAPI(P2L)—GA 3.0° TCH 20'.**RWY 30:** PAPI(P2L)—GA 3.2° TCH 22'. Tree.**SERVICE:** FUEL 100LL**AIRPORT REMARKS:** Attended irregularly. Parachute Jumping. 100LL 24 hr self serv. Rwy 12-30: rwy sfc seal-peastones.

Considerable amt of loose stones on rwy & twy. Rwy 12 has a -3 ft drop off near end of rwy, Rwy 30 has a 3 ft ditch 180 ft from end of rwy. Rwy 30 29 ft power line 1133 ft from thld left and right of centerline. 48 ft power line 1791 ft from thld left and right of centerline. Overnight tiedown fee.

AIRPORT MANAGER: 361-749-4008**WEATHER DATA SOURCES:** AWOS-3 118.425 (361) 749-0537.**COMMUNICATIONS:** CTAF 122.9® **CORPUS APP/DEP CON** 125.4**CLEARANCE DELIVERY PHONE:** For CD ctc Corpus Christi Apch at 361-299-4230.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CRP.**CORPUS CHRISTI (VH) (H) VORTACW** 115.5 CRP Chan 102 N27°54.23' W97°26.69' 097° 19.7 NM to fld. 60/9E.

TACAN AZIMUTH & DME unusable:

024°-036° byd 35 NM blo 1,700'

037°-023° byd 35 NM blo 2,000'

265°-275°

VOR unusable:

340°-005° byd 40 NM blo 7,000'

340°-005° byd 84 NM

Byd 30 NM blo 1,500'

TACAN AZIMUTH unusable:

080°-085° byd 30 NM