

ALPINE CO (See MARKLEEVILLE on page 204)

## ALTURAS

ALTURAS MUNI (AAT)(KAAT) 1 W UTC-8(-7DT) N41°28.97' W120°33.93'

KLAMATH FALLS

4378 B NOTAM FILE AAT

L-11A

RWY 13-31: H4228X50 (ASPH) S-12 MIRL

IAP

RWY 13: Road. Rgt tfc.

RWY 31: REIL. Railroad.

RWY 03-21: H2506X60 (ASPH) S-12 LIRL 0.5% up NE

RWY 03: REIL. VASI(V2L)—GA 3.0° TCH 28'. Railroad.

RWY 21: Tree. Rgt tfc.

SERVICE: FUEL 100LL, JET A LGT ACTVT REIL Rwy 03 and 31; VASI Rwy 03; MIRL Rwy 13-31; LIRL Rwy 03-21—CTAF.

AIRPORT REMARKS: Attended 1600-0100Z±. Deer on and invof arpt.

Wildlife refuges to the SW, S, and SE present potential bird hazards to acct from Oct-April. Firefighting acct seasonal May-Oct. Arrivals Rwy 21 discouraged due to school on apch. No tkf Rwy 03 to NE except during adverse wind conditions. 150' minimum alt over houses.

AIRPORT MANAGER: 530-233-2377

WEATHER DATA SOURCES: ASOS 124.175 (530) 233-7171.

COMMUNICATIONS: CTAF/UNICOM 122.8

SEATTLE CENTER APP/DEP CON 127.6

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE LKV.

LAKEVIEW (VH) (H) VORTACW 112.0 LKV Chan 57 N42°29.57'

W120°30.43' 163° 60.6 NM to fld. 7465/19E.

VOR unusable:

120°-142° byd 40 NM

143°-153° byd 117 NM

143°-153° byd 40 NM blo 11,000'

143°-153° byd 65 NM blo 14,000'

154°-160° byd 40 NM

161°-171° byd 40 NM blo 18,000'

172°-208° byd 40 NM

209°-219° byd 40 NM blo 9,000'

209°-219° byd 63 NM

220°-224° byd 40 NM

225°-236° byd 40 NM blo 15,000'

225°-236° byd 48 NM

237°-248° byd 40 NM

249°-259° byd 40 NM blo 12,000'

249°-259° byd 56 NM

260°-280° byd 40 NM

(H) DME 116.65 AAT Chan 113(Y) N41°29.00' W120°33.69' at fld. 4378. NOTAM FILE AAT.

DME unusable:

040°-130° byd 30 NM blo 17,800'

220°-230° byd 25 NM blo 10,500'

