

DORRIS

BUTTE VALLEY (A32) 5 SW UTC-8(-7DT) N41°53.24' W121°58.54'

KLAMATH FALLS

4243 B TPA-5043(800) NOTAM FILE RIU

L-21

RWY 16-34: H4300X60 (ASPH) S-30 MIRL

RWY 16: Road.

RWY 34: Fence.

SERVICE: LGT ACTIVATE MIRL Rwy 16-34 key 122.9; 5 times.

AIRPORT REMARKS: Unattended. Arpt rstd by arpt owner to acft with maximum certificated tkof weight of 12,500 lbs or less; call arpt manager 530-842-8259 for more information.

AIRPORT MANAGER: 530-842-8259

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE LMT.

KLAMATH FALLS (VH) (H) VORTACW 115.9 LMT Chan 106

N42°09.19' W121°43.65' 198° 19.4 NM to fld. 4090/17E.

VOR unusable:

050°-060° byd 30 NM blo 12,000'

060°-120° byd 25 NM blo 12,000'

126°-136° byd 40 NM blo 14,000'

126°-136° byd 97 NM

141°-149° byd 40 NM

150°-160° byd 40 NM blo 18,000'

161°-168° byd 40 NM

169°-179° byd 40 NM blo 18,000'

170°-195° byd 20 NM

180°-194° byd 40 NM

201°-266° byd 40 NM

210°-245° byd 25 NM blo 12,000'

267°-277° byd 40 NM blo 9,500'

267°-277° byd 62 NM

270°-280° byd 20 NM

278°-304° byd 40 NM

320°-050° byd 23 NM blo 12,000'

320°-050° byd 30 NM

321°-327° byd 40 NM

328°-344° byd 40 NM blo 19,000'

345°-124° byd 40 NM

TACAN AZIMUTH unusable:

105°-125° byd 7 NM blo 12,000'

153°-195° byd 20 NM blo 11,000'

210°-305° byd 25 NM blo 10,500'

320°-105° byd 13 NM blo 13,000'

320°-125° byd 20 NM

DME unusable:


105°-125° byd 7 NM blo 12,000'

153°-195° byd 20 NM blo 11,000'

210°-305° byd 25 NM blo 10,500'

320°-105° byd 13 NM blo 13,000'

320°-125° byd 20 NM



DUNSMUIR MUNI-MOTT (106) 3 N UTC-8(-7DT) N41°15.78' W122°16.32'

KLAMATH FALLS

3261 NOTAM FILE RIU

RWY 14-32: H2800X60 (ASPH) S-12.5 1.1% up NW

RWY 14: Thld dspld 635'. Trees. Rgt tfc.

AIRPORT REMARKS: Unattended. Arpt CLOSED to night ops. Arpt surrounded by high mountains. Rising terrain unlighted obstacles north and east of rwy. Use caution departing Rwy 32 due to rising slope, terrain and unlgtd obstructions north and east of rwy.

AIRPORT MANAGER: 530-859-3061

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.

ECKERT FLD (See STRATHMORE on page 289)