

RNAV (RNP) Z RWY 28L
JOHN GLENN COLUMBUS INTL (CMH)

MISSED APPROACH:
Climb to 1400 then
climbing left turn to
3000 direct BOUTN
LOM and hold.

MISSED APCH FIX

4 NM

218°

BOUTN BU

TEEZE

6000 210K

(RF REQD)

5100

101°


(3.8)

TAYZZ

1280

1548

(IAF)



COLUMBUS, OHIO
Amdr 2A 24MAR22
40°00'N-82°54'W
JOHN GLENN COLUMBUS INTL (CMH)
RNAV (RNP) Z RWY 28L