SW-4, 23 JAN 2025 to 20 FEB 2025

ARRIVAL ROUTE DESCRIPTION

From PINNG on track 292° to cross BRDEY at/above 13000 and at 250K.

LANDING RUNWAYS 7L, 7R, 8: From BRDEY on track 296° to cross WIGWM at/above 12000 and at/below 14000 and at 250K, then on track 296° to cross DDUKE at/above 10000 and at/below 12000, then on track 296° to cross RVANN at/above 8000 and at/below 9000 and at 230K, then on track 296° to cross LGACY at 7000 and at 210K, then on track 283° to VISTL, then on track 258° to cross NEELE at 7000 and at 210K, then on track 258°. Expect RADAR vectors to final approach course.

LANDING RUNWAY 25L: From BRDEY on track 326° to cross PAAAR at/above 10000 and at/below 12000 and at 230K, then on track 325° to cross PUKRE at/above 8000 and at/below 9000 and at 210K, then on track 322° to cross FINAP at/above 5000 and at/below 6000, then on track 282° track to cross GIPSE at/above 4000. Expect ILS or LOC RWY 25L approach or RADAR vectors to final approach course.

LANDING RUNWAY 25R: From BRDEY on track 326° to cross PAAAR at/above 10000 and at/below 12000 and at 230K, then on track 325° to cross PUKRE at/above 8000 and at/below 9000 and at 210K, then on track 322° to cross FINAP at/above 5000 and at/below 6000, then on track 284° to cross ZAMEX at/above 4000. Expect RNAV (GPS) Y or (RNP) Z RWY 25R approach or RADAR vectors to final approach course.

LANDING RUNWAY 26: From BRDEY on track 326° to cross PAAR at/above 10000 and at/below 12000 and at 230K, then on track 325° to cross PUKRE at/above 8000 and at/below 9000 and at 210K, then on track 322° to cross FINAP at/above 5000 and at/below 6000, then on track 292° to cross JAGAL at/above 4000. Expect ILS or LOC RWY 26 approach or RADAR vectors to final approach course.

LOST COMMUNICATIONS

LANDING RUNWAY 7L:At NEELE turn right, intercept and execute RWY 7L ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 7R:At NEELE turn right, intercept and execute RWY 7R ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 7R:At NEELE turn right, intercept and execute RWY 7R ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 8:At NEELE turn right, intercept and execute RWY 8 ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 25L:At GIPSE intercept and execute RWY 25L ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 25R:At ZAMEX intercept and execute RWY 25R RNAV (GPS)approach. If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 26:At JAGAL intercept and execute RWY 26 ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 26:At JAGAL intercept and execute RWY 26 ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.LANDING RUNWAY 26:At JAGAL intercept and execute RWY 26 ILS approach.If unable, proceed direct PXR VORTAC and hold, maintain 9000.