

MAYPORT, FLORIDA


COPTER TACAN Z RWY 23

TACAN NRB Chan 51		APCH CRS 221°		Rwy Idg 8001 TDZE 15 Arpt Elev 15	[USN]	MAYPORT NS (ADM DAVID L. MC DONALD FLD)(KNRB)	
 Visibility reduction by helicopters NA.					MISSED APPROACH: Climbing left turn to 1500 via NRB TACAN R-081 to BOLEZ and hold.		
ATIS ★ 236.775		JACKSONVILLE APP CON 124.9 308.4		TOWER ★ 118.75 239.30		GND CON 126.5 233.7	
						ASR/PAR	


CAUTION: Procedure is not authorized at night when the VGSI is inop, unless the station has an approved observer watching for marine traffic in the St. John's River Channel.

Max airspeed 90 KIAS

CRG Feeder route requires turn in hold.



EMERG SAFE ALT 100 NM 2800



MAYPORT, FLORIDA

30°23'N-81° 25'W MAYPORT NS (ADM DAVID L. MC DONALD FLD) (KNRB)

Amdt 4 05SEP24

COPTER TACAN Z RWY 23

SE-3, 23 JAN 2025 to 20 FEB 2025