


## LINSE ONE DEPARTURE (RNAV)

FREDERICK MUNI (FDK)  
FREDERICK, MARYLAND

POTOMAC DEP CON  
126.1 338.25  
ATIS  
124.875  
CLNC DEL  
127.425  
126.9 (When twr closed)  
GND CON  
127.425  
FREDERICK TOWER ★  
132.4

RNAV 1 - DME/DME/IRU or GPS.  
RADAR required.

**TOP ALTITUDE:**  
**16000**



## DEPARTURE ROUTE DESCRIPTION

TAKEOFF RUNWAY 5: Climb on heading 048° to 1100 before turning left.

TAKEOFF RUNWAY 12: Climb on heading 124° to 900 before proceeding westbound.

TAKEOFF RUNWAY 23: Climb on heading 229° to 1200 before turning right.

Climb on assigned heading for RADAR vectors to cross TERPZ at or above 11000, thence....

....then on track 330° to cross LINSE at or above 14000. Then on assigned transition. Maintain 16000, expect filed altitude 10 minutes after departure.

JERES TRANSITION (LINSE1.JERES)

MCRAY TRANSITION (LINSE1.MCRAY)