

<b>DUTCH LANDING STRIP</b> (88AK) PVT	0 N	UTC-9(-8DT)	N60°32.42' W150°52.08'	<b>ANCHORAGE</b>
300 NOTAM FILE	Not insp.			
<b>RWY 07-25:</b> 1300X100 (GRVL)				
RWY 07: Trees.				
RWY 25: Trees. Rgt tfc.				
<b>AIRPORT REMARKS:</b> Unattended.				
<b>AIRPORT MANAGER:</b> 907-398-8999				
<b>COMMUNICATIONS:</b> CTAF 122.5				
<b>COMM/NAV/WEATHER REMARKS:</b> For a toll free call to Kenai FSS dial 1-866-864-1737.				
<b>LAKEWOOD AIRSTRIP</b> (53AK) PVT	5 NE	UTC-9(-8DT)	N60°32.03' W150°51.39'	<b>ANCHORAGE</b>
299 NOTAM FILE	Not insp.			
<b>RWY 02-20:</b> 1200X60 (GRVL)				
RWY 02: Trees. Rgt tfc.				
<b>AIRPORT REMARKS:</b> Unattended. Rwy 02-20 not plowed durg winter, silty sand base unusbl durg breakup. Rwy 02-20 sand/gravel.				
<b>AIRPORT MANAGER:</b> 936-443-9072				
<b>COMMUNICATIONS:</b> CTAF 122.5				
<b>COMM/NAV/WEATHER REMARKS:</b> For a toll free call to Kenai FSS dial 1-866-864-1737.				
<b>SCOOTERS LANDING STRIP</b> (AK84) PVT	2 W	UTC-9(-8DT)	N60°31.77' W150°49.85'	<b>ANCHORAGE</b>
259 NOTAM FILE	Not insp.			
<b>RWY 08-26:</b> 2400X80 (GRVL)				
<b>AIRPORT REMARKS:</b> Unattended. PPR arpt rstd to owner or owner invited guests. No acft svcs avbl. Rwy conditions not monitored. Fly pat south of E-W rwy, twrs north. Pilots to conduct rwy visual inspection prior to use. Maintenance personnel and equipment have right of way. Wildlife inovf rwy. Be alert, dsplcd thlds exist. Trees and p-lines penetrate apch sfcs. Arpt not fenced.				
<b>AIRPORT MANAGER:</b> 907-398-9849				
<b>COMMUNICATIONS:</b> CTAF 122.5				
<b>COMM/NAV/WEATHER REMARKS:</b> For a toll free call to Kenai FSS dial 1-866-864-1737. Advisory frequency: 122.5.				
<b>STERLING AIR PARK</b> (40AK) PVT	2 NW	UTC-9(-8DT)	N60°33.45' W150°50.61'	<b>ANCHORAGE</b>
333 NOTAM FILE	Not insp.			
<b>RWY 08-26:</b> 1809X60 (GRVL)				
<b>AIRPORT REMARKS:</b> Unattended.				
<b>AIRPORT MANAGER:</b> 907-262-5100				
<b>COMMUNICATIONS:</b> CTAF 122.5				
<b>COMM/NAV/WEATHER REMARKS:</b> For a toll free call to Kenai FSS dial 1-866-864-1737.				
<b>STEVENS VILLAGE</b> (SVS)(PFSV)	1 NNE	UTC-9(-8DT)	N66°01.03' W149°03.26'	<b>FAIRBANKS</b>
328 B NOTAM FILE FAI				
<b>RWY 05-23:</b> 4000X75 (GRVL-DIRT)	MIRL			
RWY 05: REIL, PAPI(P4L)—GA 3.0° TCH 25'. Trees.				
RWY 23: REIL, PAPI(P4L)—GA 3.0° TCH 25'. Trees.				
<b>SERVICE:</b> LGT ACTVT REIL Rwy 05 and 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23—CTAF, ACTVT Rotg beacon—CTAF.				
<b>AIRPORT REMARKS:</b> Unattended. Rwy 05-23 cond not monitored, rcmd visual inspection prior to Indg. Cldw rwy located 1 NM west of Rwy 05-23. Snow removal ops during winter, monitor CTAF. Rwy 05-23 marked with lghts and cones.				
<b>AIRPORT MANAGER:</b> (907) 451-5280				
<b>COMMUNICATIONS:</b> CTAF 122.9				
<b>RADIO AIDS TO NAVIGATION:</b> NOTAM FILE FAI.				
FAIRBANKS (H) (H) VORTACW 108.6 FAI Chan 23 N64°48.00'				
W148°00.72' 320° 77.8 NM to fld. 1526/21E.				
TACAN AZIMUTH unusable:				
065°-100° byd 30 NM				
270°-330° byd 10 NM bld 10,000'				
270°-330° byd 30 NM				
<b>COMM/NAV/WEATHER REMARKS:</b> For a toll free call to Fairbanks FSS dial 1-866-248-6516.				

