

TRACY**NEW JERUSALEM** (1Q4) 7 SE UTC-8(-7DT) N37°40.67' W121°18.07'**SAN FRANCISCO**

62 TPA-862(800) NOTAM FILE RIU

L-2F, 3B**RWY 12-30:** H3530X60 (ASPH)**RWY 12:** Trees.**RWY 30:** Trees.

AIRPORT REMARKS: Unattended. Model acft activity on and in/ov abandoned rwy. Aerobatic activity north northeast of arpt and over abandoned parallel Rwy 12-30 from surface to 4,000' MSL. Parallel twy failed cond with rough/uneven sfc from extensive asph rpr and patching. Erroneous mrkgs on Rwy 12/30. Ngt opr prohibited. Standing water on parallel twy after rain. Rwy 12-30 12,500 lbs gross pavement strength provided by arpt management.

AIRPORT MANAGER: (209) 831-6215**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc NorCal Apch at 916-361-0516.**RADIO AIDS TO NAVIGATION:** NOTAM FILE MOD.

MODESTO (VH) (DH) VOR/DME 114.6 MOD Chan 93 N37°37.64' W120°57.47' 264° 16.6 NM to fld. 93/17E.
aerobatic acft wi an area defined as .5 NM rds of MOD 032028 (7.5 NM SW 022), blo 4800', avoidance advised dly sr-ss

VOR unusable:

005°-009° byd 40 NM

028°-083° byd 40 NM

092°-097° byd 40 NM

112°-121° byd 40 NM

130°-145° byd 40 NM blo 4,000'

130°-145° byd 62 NM

146°-156° byd 40 NM

170°-185° byd 40 NM

186°-196° byd 40 NM blo 5,000'

186°-196° byd 49 NM

197°-338° byd 40 NM