

TIOGA MUNI (D60) 2 SE UTC-6(-5DT) N48°22.82' W102°53.84'

2271 B NOTAM FILE GFK

RWY 12-30: H5102X75 (ASPH) S-25 MIRL 0.6% up SE

RWY 12: PAPI(P2L)—GA 3.0° TCH 26°.

RWY 30: PAPI(P2L)—GA 3.0° TCH 25°. Road.

RWY 3-21: 3200X120 (TURF) 0.6% up SW

SERVICE: S4 FUEL 100LL, JET A LGT Rwy 12-30 MIRL preset low ints, to increase ints ACTIVATE PAPI Rwy 12 and Rwy 30—CTAF.

AIRPORT REMARKS: Attended 1300-2300Z. Arpt svcs phone

701-641-6020 or 507-649-0831 on call after hrs. Fuel self svc 24 hr credit card access, full svc per attendant sked and on call aft hrs.

Confirm snow removal with arpt manager or FBO after major storm.

Birds and deer on and inof arpt. Mechanic avbl on call contact FBO at 701-664-3012. Rwy 03 twy and apron marked with reflectors.

AIRPORT MANAGER: 701-216-0036

WEATHER DATA SOURCES: AWOS-3 118.575 (701) 664-4490.

COMMUNICATIONS: CTAF 122.9

⑧ **MINNEAPOLIS CENTER APP/DEP CON** 127.6

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at


651-463-5588.

RADAR AIDS TO NAVIGATION: NOTAM FILE ISN.

WILLISTON (VL) (DH) VOR/W/DME 116.3 ISN Chan 110 N48°15.20'

W103°45.04' 069° 35.0 NM to fld. 2365/8E.

BILLINGS
H-2H, L-13E, 14F
IAP



TOMLINSON FLD (See NEW ROCKFORD on page 355)

TOWNER MUNI (D61) 1 NE UTC-6(-5DT) N48°21.57' W100°23.73'

TWIN CITIES

1484 B NOTAM FILE GFK

RWY 03-21: 2810X120 (TURF) 0.3% up NE

RWY 03: Road.

RWY 16-34: 2732X150 (TURF) LIRL

RWY 16: Road.

RWY 34: Road.

SERVICE: LGT Dusk-Dawn. ACTVT LIRL Rwy 16-34—CTAF.

AIRPORT REMARKS: Unattended. Confirm winter conditions after snowstorm with arpt manager 701-537-5137 or 701-537-3519. Rwy 03 has 140' water tower 2000' from thld 600' left of extended centerline. 3' ditch southeast end Rwy 16-34 and southwest end Rwy 03-21. Rwy 03-21 has 5 ft rvb vis sight clnc violation. Rwy 03-21 mkd 3 ft wooden red mkrs on ends and intxn. Rwy 16-34 mkd 3 ft wooden red mkrs on ends and intxn.

AIRPORT MANAGER: 701-537-3519

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

• • • • • • • • • • • • • • • • •

HELIPAD H1: H30X30 (CONC)

TRULSON FLD (See PLAZA on page 358)

TURTLE LAKE MUNI (91N) 1 SW UTC-6(-5DT) N47°30.58' W100°55.00'

TWIN CITIES

1916 NOTAM FILE GFK

RWY 08-26: 3148X120 (TURF) LIRL 0.5% up E

SERVICE: LGT ACTIVATE LIRL Rwy 08-26—CTAF.

AIRPORT REMARKS: Unattended. Confirm winter conditions with arpt manager before use due to irregular snow removal, call 701-220-0707. Deer and wildlife on and in vicinity of arpt. Rwy 08-26 sfc grass soft when wet. Rwy 08 has 10' dropoff 50' out from thld. Rwy 08-26 during daigl marked with yellow tires around lgts.

AIRPORT MANAGER: (701) 516-3826

COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.